

JAN 19 2000

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

LIBER 333 PAGE 437

#1349

For corners in

Missaukee County Located In: Corner Code #

1. Public Land Survey T 21N R 06W M-5
T R
T R
T R

2. Property Controlling S T R
in Section S T R

3. Miscellaneous S T R
Property in Sec. S T R

MISSAUKEE COUNTY MICHIGAN

RECORDED DEC 09 1999 4:10 PM

Paulyn Flare
REGISTER

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

I, J. Dean Geers, P.S., in a field survey on June, 19 99 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A	B	C	D	E	F	G	H	I	J	K	L	M
1												
2	6		5		4		3		2		1	
3												
4	7		8		9		10		11		12	
5												
6	18		17		16		15		14		13	
7												
8	19		20		21		22		23		24	
9												
10	30		29		28		27		26		25	
11												
12	31		32		33		34		35		36	
13												

A. Description of original monument and accessories and/or subsequent restoration:

- M-5) 1837 GLO Section Corner Post by John Brink, Deputy Surveyor.
10" Beech-S07W-28 lks, 11" Beech-N25W-51 lks.
- M-5) 1852 GLO Section Corner Post recovered by A. Curtis, Deputy Surveyor. 20" Y. Pine-N35E-24 lks,
8" Beech-S43E-26 lks.
- M-5) 1987 Roser survey and LCRC, Liber 1, Page 746; Drove 1 1/4" x 18" solid iron rod. 24" Maple-N46E-40.20', Power pole-S50E-53.89', 14" Maple-N70E-72.92', Set Cedar post-WEST-33'.
Restored corner based on occupation in the area.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- M-5) Section corner common to Section 12, T21N, R6W, Section 13, T21N, R6W,
Section 7, T21N, R5W, and Section 18, T21N, R5W. Found 1 1/4" x 18" rod and cedar
location post as recorded in Liber 1, Page 746. Corner is ± 3' southerly of centerline road
east; ± 13' northwesterly of centerline trail southwest; ± 12' westerly of centerline trail
north-northwesterly. This corner is accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- M-5) Found 1 1/4" x 18" rod. Replaced with 1/2" x 36" rebar and Missaukee County Monument.

- *S45E 53.92' Set nail above PK in northeast face of power pole.
N62W 25.28' Set nail in southwest face of twin 6" cherry.
*N55E 39.81' Set nail in south face 26" silver maple.
*N76E 73.05' Set nail in north face 16" silver maple.

*Previous Witness



Peer Group Reviewed and Approved

Date: 12-7-99
J. Dean Geers
J. Dean Geers, Missaukee Co. Representative

Signed by *J. Dean Geers*
Surveyor's Michigan License No. 33977

Date 11-23-99