(

DEC 0 7 1994

Surveyor's Michigan License No. 33977

LIBER	390 _{PA}	_{GF} 3 <i>0</i>
LIBER	PA	GEO

1. Public Land Survey T 21N R 8W K-9 T R T R T R T R T R T R T R T R T R T		DEC 0 1 133		ement of Act 74 Mich PA	
MISSAUKEE COUNTY MICHO Commit Public Land Survey 1 21N g 8W K-9 2 Property Controlling	For corne	rs incommiss	ION	ement of Act 74, which. F.A.	1970
The Resistance of the Standard	Miss	aukee		Corner Code ##	MISSAUKEE COUNTY MICHIGA
Mescellaneous Property in Sec. S T R R Register of Deeds Stamp & File Number Property in Sec. S T R R Register of Deeds Stamp & File Number Property in Sec. S T R R Register of Deeds Stamp & File Number Property in Sec. S T R R Register of Deeds Stamp & File Number Property in Sec. S T R R Register of Deeds Stamp & File Number Property in Sec. S T R R Register of Deeds Stamp & File Number Register	1. Public	: Land Survey	T R T R		CONDED OCT 2 8 1994 /
Miscellareous Property in Sec. S T R R Register of Deeds Stamp & File Number Property in Sec. S T R R Register of Deeds Stamp & File Number Property in Sec. S T R R Register of Deeds Stamp & File Number Property in Sec. S T R R Register of Deeds Stamp & File Number Property in Sec. S T R R Register of Deeds Stamp & File Number Register Regi	2 Prope	rty Controlling			(awayer Flore
4. Lot No			_		AEOIS II
4. Lot No					Register of Deeds Stamp & File Number
t. J. Dearn Geers in a fired survey on October 7. (a) Dearn Geers in a fired survey on October 7. (b) Dearn Geers in a fired survey on October 7. (c) Dearn Geers in a fired survey on October 7. (d) Provide a survey instruction of the United States Department of the Interior. Remained in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior. Remained in the Conformance with the rules of the Michigan Board of Land Surveyors or by a decree of a Court of Law and/or that the corner points mentioned in the Surveyor of the Conformance with the rules of the Michigan Board of Land Surveyors or by a forcer of a Court of Law and/or that the corner points mentioned in the survey of the Conformance with the rules of the Michigan Board of Land Surveyors or by a forcer of a Court of Law, established, re-established, monumented. Re-monumented. Re-monumented recovered, found as expressed below. NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. A Description of original monument and accessories and/or subsequent restoration: K-9) 1853 GLO post by John Brink, Deputy Surveyor Birch 14 S 55 W 15, Hemlock 16 S 44 1/4 E 19 K-9) 1890, 1892 Beuthien Survey: Corner was used but no witnesses given. K-9) 1972 M. McClung LCRC Liber 1, Page 110: Found monument box, no witnesses given. K-9) 1978 M. McClung LCRC Liber 1, Page 566: Found monument box, no witnesses given. K-9) 1978 M. McClung LCRC Liber 1, Page 566: Found monument box, no witnesses given. K-9) Section corner evidence found and/or method applied in restoring or reestablishing corner: K-9) Section corner evidence found and/or method applied in restoring or reestablishing corner: K-9) Section corner evidence found and/or method applied in restoring or reestablishing corner: K-9) Section corner evidence found and/or method applied in restoring or reestablishing corner: K-9) Section corner c		•			
do hereby certify that under requirements of PA 74. Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as recurred in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or year descreed 16 count of Laws, established. The commentation mentioned the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or year descreed 16 count of Laws, established. The commentation removement of the Count of Laws, established the momentation removement of the Count of Laws, established. The commentation of the Michigan Boad of Land Surveyors of by a Decree of a Count of Laws, established. The commentation of the Count of Laws, established the Count of Laws, established the commentation of the Count of Laws, established. The commentation of the count of Laws, established the commentation of the count of Laws, established to the Count of the Count of Laws, established to the Count of the Count of Laws, established to the Count of the Count of the Count of Laws, established to the Count of the Count of Laws, established to the Count of the Count					
do hereby certify that under requirements of Pa 74, Michigan Pa of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rubes therefore as a required in the current manual of survey instructions of the United States bepartment of the interior. Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law and conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a court of Law and conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a court of Law and conformance with the rules of the Michigan Board of Land Surveyors or appear to the position of original monument and accessories and/or subsequent restoration. K-9) 1853 GLO post by John Brink, Deputy Surveyor Birch 14 S 55 W 15, Hemlock 16 S 44 1/4 E 19 K-9) 1890, 1892 Beuthien Survey: Corner was used but no witnesses given. K-9) 1978 M. McClung LCRC Liber 1, Page 110: Found monument box, no witnesses given. K-9) 1978 M. McClung LCRC Liber 1, Page 566: Found monument box, no witnesses given. K-9) Section corner evidence found and/or method applied in restoring or reestablishing corner: K-9) Section corner common to Sections 23, 24, 25 and 26 Found 1" O.D. pipe in monument box per Liber 1, Page 566 and is accepted as a careful and faithful perpetuation of the position of the original corner. Corner is in the Centerline of the East-West road and in the Centerline of the road to the South. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner. K-9) Set 1/2" Iron and Missaukee Co. monument in monument box N 04 E - 57.70 - Set Iron in Centerline Trail				•	
on this certificate. A. Description of original monument and accessories and/or subsequent restoration: K-9) 1853 GLO post by John Brink, Deputy Surveyor Birch 14 S 55 W 15, Hemlock 16 S 44 1/4 E 19 K-9) 1890, 1892 Beuthien Survey: Corner was used but no witnesses given. K-9) 1972 M. McClung LCRC Liber 1, Page 110: Found monument box, no witnesses given. K-9) 1978 M. McClung LCRC Liber 1, Page 566: Found monument box, no witnesses given. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: K-9) Section corner common to Sections 23, 24, 25 and 26 Found 1" O.D. pipe in monument box per Liber 1, Page 566 and is accepted as a careful and faithful perpetuation of the position of the original corner. Corner is in the Centerline of the East-West road and in the Centerline of the road to the South. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner. K-9) Set 1/2" Iron and Missaukee Co. monument in monument box N 04 E - 57.70 - Set Iron in Centerline Trail N 44 W - 47.18 - Set Iron on South side of Tele Riser S 40 E - 47.18 - Set Iron on South side of Tele Riser S 40 E - 47.18 - Set Iron on South side of Tele Riser S 40 E - 47.18 - Set Iron on South side of Tele Riser S 40 E - 47.18 - Set Iron in East end 24" CMP S 50 W - 46.60 - Set Pk-nail in Bast end 24" CMP S 50 W - 23.04 - 12" Apple	do hereby of in lines 1 a current mai Manageme above were Court of L	certify that under requind 2 above were in conual of survey instruction to by a decree of a Control or by a decree of a Conformance with Law; established, re-	irements of P.A. 74, Michigan P.A. conformance with regulations ar tions of the United States Depar Court of Law and/or that the corne the rules of the Michigan Board	of 1970, the corner points mentioned rules therefore as required in the timent of the Interior, Bureau of Laier points mentioned in lines 3, 4 and of Land Surveyors or by a Decree o	ed he he nd 7 15 16 15 14 15 15 14 15 15 15 15 15 15 15 15 15 15 15 15 15
A Description of original monument and accessories and/or subsequent restoration: K-9) 1853 GLO post by John Brink, Deputy Surveyor Birch 14 S 55 W 15, Hemlock 16 S 44 1/4 E 19 K-9) 1890, 1892 Beuthien Survey: Corner was used but no witnesses given. K-9) 1972 M. McClung LCRC Liber 1, Page 110: Found monument box, no witnesses given. K-9) 1978 M. McClung LCRC Liber 1, Page 566: Found monument box, no witnesses given. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: K-9) Section corner common to Sections 23, 24, 25 and 26 Found 1" O.D. pipe in monument box per Liber 1, Page 566 and is accepted as a careful and faithful perpetuation of the position of the original corner. Corner is in the Centerline of the East-West road and in the Centerline of the road to the South. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner. K-9) Set 1/2" Iron and Missaukee Co. monument in monument box N 04 E - 57.70 - Set Iron in Centerline Trail N 44 W - 47.18 - Set Iron on South side of Tele Riser S 40 E - 47.18 - Set Iron on South side of Tele Riser S 40 E - 47.18 - Set Iron on South side of Tele Riser S 40 E - 47.18 - Set Iron on South side of Tele Riser S 40 E - 47.18 - Set Pk-nail in East end 24" CMP S 50 W - 46.60 - Set Pk-nail in East end 24" CMP S 50 W - 46.60 - Set Pk-nail in East end 24" CMP S 33 W - 123.04 - 12" Apple			ners, all in the same town a	nd range, may be recorded	
K-9) 1853 GLO post by John Brink, Deputy Surveyor Birch 14 S 55 W 15, Hemlock 16 S 44 1/4 E 19 K-9) 1890, 1892 Beuthien Survey: Corner was used but no witnesses given. K-9) 1972 M. McClung LCRC Liber 1, Page 110: Found monument box, no witnesses given. K-9) 1978 M. McClung LCRC Liber 1, Page 566: Found monument box, no witnesses given. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: K-9) Section corner common to Sections 23, 24, 25 and 26 Found 1" O.D. pipe in monument box per Liber 1, Page 566 and is accepted as a careful and faithful perpetuation of the position of the original corner. Corner is in the Centerline of the East-West road and in the Centerline of the road to the South. C. Description of monument for corner and accessories established to perpetuate locating the position of the Centerline of the Found to the South. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: K-9) Set 1/2" Iron and Missaukee Co. monument in monument box N 04 E - 57.70 - Set Iron in Centerline Trail N 44 W - 47.18 - Set Iron on South side of Tele Riser S 40 E - 47.18 - Set Pk-nail in East end 24" CMP S 50 W - 46.60 - Set Pk-nail in East end 24" CMP S 33 W - 123.04 - 12" Apple					
Birch 14 S 55 W 15, Hemlock 16 S 44 1/4 E 19 K-9) 1890, 1892 Beuthien Survey: Corner was used but no witnesses given. K-9) 1972 M. McClung LCRC Liber 1, Page 110: Found monument box, no witnesses given. K-9) 1978 M. McClung LCRC Liber 1, Page 566: Found monument box, no witnesses given. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: K-9) Section corner common to Sections 23, 24, 25 and 26 Found 1" O.D. pipe in monument box per Liber 1, Page 566 and is accepted as a careful and faithful perpetuation of the position of the original corner. Corner is in the Centerline of the East-West road and in the Centerline of the road to the South. C. Description of monument for corner and accessories established to perpetuate localing the position of the corner. K-9) Set 1/2" Iron and Missaukee Co. monument in monument box N 04 E - 57.70 - Set Iron in Centerline Trail N 44 W - 47.18 - Set Iron on South side of Tele Riser S 40 E - 47.18 - Set Iron on South side of Tele Riser S 40 E - 47.18 - Set Pk-nail in East end 24" CMP S 50 W - 46.60 - Set Pk-nail in West end 24" CMP S 33 W - 123.04 - 12" Apple	A. Descr	iption of original m	onument and accessories an	d/or subsequent restoration:	
K-9) 1972 M. McClung LCRC Liber 1, Page 110: Found monument box, no witnesses given. K-9) 1978 M. McClung LCRC Liber 1, Page 566: Found monument box, no witnesses given. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: K-9) Section corner common to Sections 23, 24, 25 and 26 Found 1" O.D. pipe in monument box per Liber 1, Page 566 and is accepted as a careful and faithful perpetuation of the position of the original corner. Corner is in the Centerline of the East-West road and in the Centerline of the road to the South. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner. K-9) Set 1/2" Iron and Missaukee Co. monument in monument box N 04 E - 57.70 - Set Iron in Centerline Trail N 44 W - 47.18 - Set Iron on South side of Tele Riser S 40 E - 47.18 - Set Pk-nail in East end 24" CMP S 50 W - 46.60 - Set Pk-nail in West end 24" CMP S 33 W - 123.04 - 12" Apple	K-9)	1853 GLO pos	t by John Brink, Deputy Bir	Surveyor rch 14 S 55 W 15, Hemlo	ck 16 S 44 1/4 E 19
K-9) 1978 M. McClung LCRC Liber 1, Page 566: Found monument box, no witnesses given. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: K-9) Section corner common to Sections 23, 24, 25 and 26 Found 1" O.D. pipe in monument box per Liber 1, Page 566 and is accepted as a careful and faithful perpetuation of the position of the original corner. Corner is in the Centerline of the East-West road and in the Centerline of the road to the South. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner. K-9) Set 1/2" Iron and Missaukee Co. monument in monument box N 04 E - 57.70 - Set Iron in Centerline Trail N 44 W - 47.18 - Set Iron on South side of Tele Riser S 40 E - 47.18 - Set Pk-nail in East end 24" CMP S 50 W - 46.60 - Set Pk-nail in West end 24" CMP S 33 W - 123.04 - 12" Apple	K-9)	1890, 1892 Be	uthien Survey: Corner v	was used but no witnesses a	given.
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: K-9) Section corner common to Sections 23, 24, 25 and 26 Found 1" O.D. pipe in monument box per Liber 1, Page 566 and is accepted as a careful and faithful perpetuation of the position of the original corner. Corner is in the Centerline of the East-West road and in the Centerline of the road to the South. C. Description of monument for corner and accessories established to perpetuate localing the position of the corner. K-9) Set 1/2" Iron and Missaukee Co. monument in monument box N 04 E - 57.70 - Set Iron in Centerline Trail N 44 W - 47.18 - Set Iron on South side of Tele Riser S 40 E - 47.18 - Set Pk-nail in East end 24" CMP S 50 W - 46.60 - Set Pk-nail in West end 24" CMP S 33 W - 123.04 - 12" Apple	K-9)	1972 M. McC	lung LCRC Liber 1, Pag	e 110: Found monument b	ox, no witnesses given.
Found 1" O.D. pipe in monument box per Liber 1, Page 566 and is accepted as a careful and faithful perpetuation of the position of the original corner. Corner is in the Centerline of the East-West road and in the Centerline of the road to the South. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner. K-9) Set 1/2" Iron and Missaukee Co. monument in monument box N 04 E - 57.70 - Set Iron in Centerline Trail N 44 W - 47.18 - Set Iron on South side of Tele Riser S 40 E - 47.18 - Set Pk-nail in East end 24" CMP S 50 W - 46.60 - Set Pk-nail in West end 24" CMP S 33 W - 123.04 - 12" Apple			-		
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner. K-9) Set 1/2" Iron and Missaukee Co. monument in monument box N 04 E - 57.70 - Set Iron in Centerline Trail N 44 W - 47.18 - Set Iron on South side of Tele Riser S 40 E - 47.18 - Set Pk-nail in East end 24" CMP S 50 W - 46.60 - Set Pk-nail in West end 24" CMP S 33 W - 123.04 - 12" Apple	K-9)	Section corner	common to Sections 23,	24, 25 and 26	
N 04 E - 57.70 - Set Iron in Centerline Trail N 44 W - 47.18 - Set Iron on South side of Tele Riser S 40 E - 47.18 - Set Pk-nail in East end 24" CMP S 50 W - 46.60 - Set Pk-nail in West end 24" CMP S 33 W - 123.04 - 12" Apple		careful	and faithful perpetuation	of the position of the orig	inal corner. Corner is in the
N 04 E - 57.70 - Set Iron in Centerline Trail N 44 W - 47.18 - Set Iron on South side of Tele Riser S 40 E - 47.18 - Set Pk-nail in East end 24" CMP S 50 W - 46.60 - Set Pk-nail in West end 24" CMP S 33 W - 123.04 - 12" Apple					
N 04 E - 57.70 - Set Iron in Centerline Trail N 44 W - 47.18 - Set Iron on South side of Tele Riser S 40 E - 47.18 - Set Pk-nail in East end 24" CMP S 50 W - 46.60 - Set Pk-nail in West end 24" CMP S 33 W - 123.04 - 12" Apple	C Descri	intion of monument	for corner and accessories	established to perpetuate loca	ling the position of the corner:
N 04 E - 57.70 - Set Iron in Centerline Trail N 44 W - 47.18 - Set Iron on South side of Tele Riser S 40 E - 47.18 - Set Pk-nail in East end 24" CMP S 50 W - 46.60 - Set Pk-nail in West end 24" CMP S 33 W - 123.04 - 12" Apple Peer Group Reviewed and Approved Date: 10-26-94 J. Dean Geers, Missaukee Co. Representative SURVEYOR NO. SURVEYOR NO. 33977				_	
S 33 W - 123.04 - 12" Apple EAN NO SURVEYOR NO. 3977	K-9)	N 04 E - 57.70 - Set Iron in Cent N 44 W - 47.18 - Set Iron on Sou S 40 E - 47.18 - Set Pk-nail in E		terline Trail oth side of Tele Riser East end 24" CMP	Date: 10 - 26 - 54 J. Dean Geers, Missaukee Co, Repuesentative
9/9/01					EAN ERS
	Signed by	$\mathcal{O}\mathcal{A}$	Dan Dung	Date8/	

FORM APPROVED BY MICHIGAN STATE BOARD OF LARD SUMPTONS, JAN. 28, 19
REVISED MAY 14, 19
REVISED JAN., 19