

SURVEY & REMONUMENTATION

JAN 27 1999

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

LIBER 323 PAGE 1233

1284

For corners in

<u>Missaukee</u> (County)	Located In:	Corner Code #
1. Public Land Survey	T <u>22N</u> R <u>06W</u>	<u>D-13</u>
	T <u> </u> R <u> </u>	<u> </u>
	T <u> </u> R <u> </u>	<u> </u>
	T <u> </u> R <u> </u>	<u> </u>
2. Property Controlling in Section	S <u> </u> T <u> </u> R <u> </u>	<u> </u>
	S <u> </u> T <u> </u> R <u> </u>	<u> </u>
3. Miscellaneous Property in Sec.	S <u> </u> T <u> </u> R <u> </u>	<u> </u>
	S <u> </u> T <u> </u> R <u> </u>	<u> </u>

MISSAUKEE COUNTY MICHIGAN

RECORDED NOV 13 1998

950
PA

Paulyn Flare
REGISTER

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

I, J. Dean Geers, P.S., in a field survey on June, 19 98 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

- D-13) 1837 GLO Quarter Section Post by John Brink, Deputy Surveyor; Hemlock 9-N31½E-21, Sugar 11-N66W-48
- D-13) 1893 County Surveyor; Corner was used but no description or witnesses provided

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- D-13) Quarter Section Corner common to Section 32, T22N, R6W and Section 5, T21N, R6W. No monumentation or evidence of the corner was found except for an existing fence corner. There are old fence lines extending in all four directions from the corner and there are eight line fences to the East and West. I re-established the corner at the fence line intersection. This corner is accepted as the last available evidence of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- D-13) Set 1/2" x 18" Rebar with Missaukee County Monument
- | | | |
|------|--------|----------------|
| N80W | 4.10 | 10" Elm |
| N80W | 10.83 | 8" Elm |
| S10W | 208.02 | 10" Cherry |
| S82E | 171.07 | 5" Twin Cherry |
| N05E | 186.39 | 8" Cherry |

Peer Group Reviewed and Approved

Date: 10-2-98
J. Dean Geers
J. Dean Geers, Missaukee Co. Representative

Signed by

Date 11-2-98

Surveyor's Michigan License No. 33977

