

OCT 24 2000

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

#1095

LIBER 308 PAGE 888

For corners in

Missaukee County
(County)

Located In:

Corner Code #

1. Public Land Survey

T 22N R 8W

F-13

2. Property Controlling
in Section

S

T R

3. Miscellaneous
Property in Sec.

S

T R

4. Lot No. , Recorded Plat

5. Private Claims

MISSAUKEE COUNTY MICHIGAN

RECORDED DEC 30 1996 4:30 PM

Carolyn Klare
REGISTER
Register of Deeds Stamp & File
Number

I, Daniel E. Schripsema, in a field survey on October 1, 1996 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6			5		4		3		2		1	
3													
4	7			8		9		10		11		12	
5													
6	18			17		16		15		14		13	
7													
8	19			20		21		22		23		24	
9													
10	30			29		28		27		26		25	
11													
12	31			32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

- F-13) 1837 GLO survey by John Brink, Deputy Surveyor - set quarter Section post - Beech 13" N20 1/2 E 30, Beech 10" N36W 17
1909 County surveyor records, pg. 66, cedar stake - Pine 36" S33 3/4 W 70 1/2, Pine 36" S11 1/2 E 96 1/2, Pine 36" N8E 67 1/2
1966 MDOT corner wit. - C. F. Roser, LCRC No. 223, found 1" iron Pin & one old wit., 13" maple S41W 81.28',
power pole N43W 40.85', tel. Pole S55E 46.73', B. spike. Due N. 17.00'
1978 J. L. Wilcox and Assoc., Inc. survey S1, pg. 421
1993 Daniel E. Schripsema survey S3, pg 192 - 194

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- F-13) Quarter 1/4 corner common to Section 33, T 22N, R8W, and Section 4, T21N, R8W, found 1" iron pin. This corner is accepted as a careful and faithful perpetuation of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set Miss. Co. remonumentation cap on existing iron.
S36E 44.01' Sign Post
S37E 52.37' Sign Post
N47W 40.66' Power Pole (Fd Nail)
S36W 81.65' 22" Maple
N06E 30.60' East Post on Sign

Peer Group Reviewed and Approved

Date: 12-30-96
J. Dean Geers, Missaukee Co. Representative

Signed by DANIEL

SCHRIPEMA

LAND

SURVEYOR

No. 24617

REGISTERED LAND SURVEYOR

Date 12-30-96