

OCT 24 2000

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

#1096

LIBER 308 PAGE 889

Missaukee County (County) Located In: Corner Code #

1. Public Land Survey T 22N R 8W G-13
T R
T R
T R
T R

2. Property Controlling S T R
in Section S T R

3. Miscellaneous S T R
Property in Sec. S T R

MISSAUKEE COUNTY MICHIGAN

RECORDED DEC 30 1996 430 P.M.

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat
5. Private Claims

I, Daniel E. Schripsema, in a field survey on October 1, 1996 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

G-13) 1837 GLO survey by John Brink, Deputy Surveyor, set post corner Sections 33 & 34 - Beech 12 N70E 33, Hemlock 11 N73½ W 19 1909 County Surveyor records pg. 66, Cedar stake - telephone pole N11E 71, fence post (cor.) S00-30°W 32 1912 County Surveyor records, iron stake - Pine St. 30 N46W 62, Tel. pole N61E 79 1966 MDOT corner witness- C. F. Roser, LCRC No. 222 - Found ½" iron pin (20" long) - Cor. Fence post N50W 48.65', power pole N17E 57.73', telephone pole Due south 29.08', Ctr. Exist. E-W due North 1', Bit. Road B. spike. Due North 17.00' 1974 J. L. Wilcox & Assoc., Inc., LCRC No. 166, fd iron in mon. box, Due South Tel. pole 28.88', N35E P. pole 49.23' 1974 J. L. Wilcox & Assoc., Inc., survey S1, pg. 167 1978 J. L. Wilcox & Assoc., Inc., survey S1, pg. 421 MDOT right of way map, file no. 57-R-2, proj. no. 57-6, control Section 57021, sheet 32

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

G-13) Section corner common to Section 33 & 34, T22N, R8W and Section 3 & 4, T21N, R8W. Found ½" iron pin 1' south of centerline of old M-55. This corner in accepted as a careful and faithful perpetuation of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set Miss. Co. remonumentation cap on existing iron

S01E 28.91' Cut Off Tele. Pole
S50W 81.24' 6" Maple
N33E 55.48' Power Pole
N50W 143.47' 14" Maple

Peer Group Reviewed and Approved

Date: 12-30-96

J. Dean Geers, Missaukee Co. Representative

Signed by Daniel E. Schripsema

Date 12-30-96

Surveyor's Michigan License No. 24617

