LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

Missaukee (County)	Located In	Corner Code #	
 Public Land Survey Property Controlling in Section Miscellaneous Property in Section 	T 23N R 5W T R S T R R S T R R S T R	L7	Register of Deeds Stamp & File Number
4. Lot No:	Recorded Plat:		ABCDEFGHIJKLM
5. Private Claims:			
requirements of PA 74, Mic and 2 above were in confor the current manual of sun Interior, Bureau of Land Ma corner points mentioned in of the Michigan Board of	rield survey on Oct. 22, 2014 do here chigan PA of 1970, the corner points remance with regulations and rules there vey instructions of the United States inagement or by a decree of a Court of lines 3, 4 and 5 above were in conform Land Surveyors or by a Decree of monumented, recovered, found as exceptions.	mentioned in lines 1 refore as required in Department of the Law and/or that the nance with the rules of a Court of Law;	3 4 7 8 9 10 11 12 12 15 16 18 17 17 16 15 14 13 17 18 19 20 21 22 23 24

A. Description of original monument and accessories and/or subsequent restoration:

NOTE: Not more than 2 corners, all in the same town and range, may

be recorded on this certificate.

L7 - 1852 - GLO - Set Post - A. Curtis - 1) W. Pine 15" N45°W 21 L.; 2) W. Pine 14" S65°E 20 L.

- 1912 - Miss. Co. Surveyor Notes - Book 23, Page 59 - states "old bearings OK";
- 1912 - Miss. Co. Surveyor Notes - Book 24, Pages 56 & 61 - states "OB. OK.";
3) NB. WPS 20" N28°W 35 L. - Dist. E-40.07 & W-40.06

- 1980 - LCRC #581 - J. Wilcox (PS #14102) - Set 1/2" Iron by retrace Beuthien 1912

4) S26°E 31.25' Power Pole; 5) S53°W 36.60' 4" J. Pine; 6) N08°W 55.70' 16" J. Pine; 7) N62°E 67.58' Power Pole

- 1998 – LCRC #1268 – C. W. McVean – (PS #39088). No Co. evidence was found. Wilcox iron not found, apparently plowed out. Set 4" DNR A.C. in 4" x 1' PVC with concrete on 1" x 3' long iron pipe from 3 Record LCRC witnesses. CL. E-W gravel Rd. is 7'± N. and tree line S. with wire is 9'± E. Fits old Co. survey dist. E & W. Monument accepted as the best available evidence of the position of the original corner. 4" DNR Mon. with ring of stones. Set carsonite post with location tag 40' North. 8) N52°W 75.70' to set nail and tag in SW side 11" R. Pine scribed 'XBT'; 6) N15°W 55.68' to set nail and tag in W. side 20" J. Pine scribed 'XBT'; 7) N57°E 67.61' to set nail and tag in SE side Utility Pole; 4) S30°E 31.17' to set nail and tag in W. side Utility Pole; 9) S42°W 42.23' to set nail and tag in SE side 1" R. Pine

10

11 12

- B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
- L7 1/4 Corner common to Section 13 & 24, T23N, R5W Found DNR Monument bent and disturbed. Monument apparently frost heaved and hit by grader. Replaced DNR Monument with 2 1/2" Missaukee County remonumentation brass cap on 5/8" x 34" long rebar per 4 record witnesses. Condition of witnesses as follows: #1, 2, 3, 5, and 9 are gone. #4, 6, 7, and 8 are OK. Missaukee County monument accepted as the best available evidence of the position of the original corner.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- L7 Stamped 2 ½" Missaukee County Remonumentation Brass Cap on 5/8" x 34" long iron rebar 0.9' below gravel road surface. Placed stones and concrete at base of monument and 3" x 6" of PVC filled with concrete around the cap. North 40.00' to set 2" Aluminum Cap on 5/8" x 34" rebar on line with Blue Carsonite post with location tag.

N52°W 75.70' to fd. Nail and Tag (N & T) in SW side 18" Red Pine (#8) N15°W 55.68' to fd. N & T in W. side 22" Jack Pine (#6)

N57°E 67.61' to fd. N & T in SE side Utility Pole (#7) S30°E 31.17' to fd. N & T in W. side Utility Pole (#4)

Surveyor's Michigan License No.: 39088

8/2014

MICHIG **CRAIG W** MCVEAN **PROFESSIONAL** SURVEYOR No. 39086 POFE SSION