

#1008

## LIBER 300 PAGE 605

JAN 3 0 1996

## LAND CORNER RECORDATION CERTIFICATE COMMISSION Filing Requirement of Act 74, Mich. P.A. 1970

i di comero m										
Missaukee (County)	Located In:	Corner Code ##		MISS	AUKi	ΞŒ	UNI	ΥW	H()II	a jel
1. Public Land Survey	T R T R T R			2600AE						
<ol> <li>Property Controllin in Section</li> <li>Miscellaneous Property in Sec.</li> </ol>			Regist	der of l						
	, Recorded Plat			А В	c c	) E	FG	н	ı J	Κı
	, in a field survey onSet			2 - 6 - 3 - + 4 - 7 - 5 - +	5		9 —	-3 -10		
in lines 1 and 2 above we current manual of survey Management or by a decrabove were in conformant.	ler requirements of P.A. 74, Michigan Pivere in conformance with regulations instructions of the United States Depiee of a Court of Law and/or that the conce with the rules of the Michigan Boar and, re-established, monumented, re-	and rules therefore as required in partment of the Interior, Bureau of L rner points mentioned in lines 3, 4 a rd of Land Surveyors or by a Decree	the and nd5 of a d as	6 18- 7 8 19- 9 0 30-	29	1 2	6	-15 -22 -27	23	, <del> </del>
NOTE: Not more that on this certification	n 4 corners, all in the same town cate.	and range, may be recorded	1	231_	32		33-	-34	3:	<del></del>
A. Description of orig	ginal monument and accessories a	and/or subsequent restoration:								

- E-13) 1837 GLO Section post by John Brink, Deputy Surveyor; Maple 10-N 18° E- 46, Hemlock 10- N 87° W-39
- E-13) 1915 Beuthien Survey in Section 32, T23N, R5W, Found Old Bearing Tree, set new post, Tam-S 12° W-35
- E-13) 1958 MDOT Survey M-55, F 388(2); No Corner shown.
- E-13) 1974 Wilcox Survey, Liber S-1, Page 170; Set RR spike in centerline M-55 by single prop. East and West; S 70° E-115.67-P. Pole, N 43° E-42.80- chiseled "x" in East end culv., N 15° E-34.77- chiseled "x" in west end culv.
- E-13) 1974 Wilcox LCRC, Liber 1, Page 168; recorded corner per survey Liber S-1, Page 170
- E-13) 1989 Cavanagh Survey, Liber S-2, Page 503; Found corner per LCRC Liber 1, Page 168
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
  - E-13) Section corner Common to Sections 32 & 33, T23N, R5W and Sections 4 & 5, T22N, R5W. Found 1" bar in Mon. box in centerline of East-West Road as recorded in LCRC Liber 1, Page 168. This corner is accepted as a careful and faithful reestablishment of the position of the original corner.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
  - E-13) Set 2½" Brass Missaukee County Mon. on 1/2" Iron in Mon. Box
    S 29° E 85.03' 6" Maple
    S 02° E 43.42' P. Pole
    S 04° W 50.00' Found Iron
    N 13° W 48.88' P. Pole
    S 60° E 115.67 P. Pole

Peer Group Reviewed and Approved
Date: 12-6-95

J. Dean Geers, Missaukee Co. Representative

Signed by Date	12-22-95
200.000	FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN