

MAY 16 1997

COMMISSIONER

Montmorency County Remonumentation

Liber 00012 Page 0214

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

MONTMORENCY

(County)

ALBERT TWP.

1. Public Land Survey

Located In:

Corner Code =#

T 29N R 2E

F - 1

T R

T R

T R

T R

2. Property Controlling

S T R

in Section

S T R

3. Miscellaneous

S T R

Property in Sec.

S T R

STATE OF MICHIGAN
MONTMORENCY COUNTY
Recorded & Filed

11-01-1996 09:43:29

A. PANGAM-MCELROY
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

	A	B	C	D	E	F	G	H	I	J	K	L	N
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, DONALD E MARLATT, in a field survey on MAY 30, 1996

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

F - 1 NORTH $\frac{1}{4}$ CORNER SEC. 4

NO CORNER SET ON ORIGINAL SURVEY

ACT 74 BY KEN OSTLING L. 1, P.204, 3-1-1978 . SET DNR MONUMENT BY S.P. METHOD.

DNR SURVEY SEPT. 1977.

4"MAPLE S43°E 34.8'

6"W.OAK S62°W 42.72'

SET RED TOP POST

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

F - 1 NORTH $\frac{1}{4}$ CORNER OF SEC. 4

FOUND DNR MONUMENT

S43°W 12"OAK 29.25'

N16°W 8"OAK 30.4'

S40°E 16"PINE STP. BLAZE 44'

S. $\frac{1}{4}$ COR. SEC. 33, T30N, R2E 16.2' WEST

APPROVED BY
PEER GROUP

JUN 7 04

L.S.B.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

F - 1 NORTH $\frac{1}{4}$ COR. SEC. 4, T29N, R2E.

LEFT DNR MONUMENT IN PLACE (1"PIPE WITH 4"CAP)

S87°E 16"OAK 20.81'

N30°W 6"OAK 5.07'

S85°E 8"MAPLE 17.78'

S43°W 12"OAK 29.25'

N16°W 8"OAK 30.4'

WITNESSES MARKED WITH 30 PENNY SPIKES & P.S. TAGE #18660.

APPROVED BY PEER GROUP JUNE 7, 1996 AS A CAREFUL AND FAITHFUL ESTABLISHMENT OF THE POSITION OF THE CORNER.

Signed by Donald E Marlatt

Date 10-28-1996

Surveyor's Michigan License No. 18660

