LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

Received MONTMORENCY COUNTY, MI 01-24-2012 09:37 cm.

For Corners In: Montmorency	Łocated In		Corner Code #	
(County)				
1. Public Land Survey		T	R	
Property Controlling in Section	s	Т	R	
Miscellaneous Property in Section	s	Т	R	
	S 19 S 19	T 29 N T 29N	R 03E	1 4
4. Lot No:	Recorded Plat:			
5. Private Claims:				
I, <u>Carl T. Kiiskila</u> , in a field requirements of PA 74, Mic	survey on higan PA o	<u>January, 9-20</u> f 1970, the co	012 do here rner points i	by state that under mentioned in lines 1


201200049474
Filed for Record in
MONTMORENCY COUNTY, M.C
TERESA WALKER, REGISTER OF DEEDS
01-24-2012 At 09:39:31 am.
LAND CORNER 14.00
Liber 1 Page 762 - 762

Instrument 201200049476 Liber Pase 1 762

Register of Deeds Stamp & File Number

I, <u>Carl T. Kiiskila</u>, in a field survey on <u>January</u>, <u>9 2012</u> do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.



- A. Description of original monument and accessories and/or subsequent restoration:
 - 1 West 1/16 corner common to Sections 18&19, T29N,R03E

4 - NW 1/16 Corner of section 19, T29N,R03E

This corner position was not established during the original Government survey.

This corner position was not established during the original Government survey.

1971 Delmer Porter P.S.#15410 set a concrete monument per B.L.M. instructions for the subdivision of a section.

1971 Delmer Porter P.S.#15410 set a concrete monument per B.L.M. Instructions for the subdivision of a section.

- B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:
 - 1 West 1/16 corner common to Sections 18&19, T29N,R03E

4 - NW 1/16 Corner of section 19, T29N,R03E

Found a concrete monument fitting standard B.L.M. instructions for subdivision of a section,

Found a concrete monument fitting standard B.L.M. instructions for subdivision of a section.

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
 - 1 West 1/16 comer common to Sections 18&19, T29N,R03E Added P.S. cap #33981 to found concrete monument.

4 - NW 1/16 Corner of section 19, T29N,R03E Added P.S. cap #33981 to found concrete monument.

Wit: N40°E 6,49' set N&T on NW side 7" W. Pine S60°E 2.82' set N&T N side 2" S. Maple S10°W 25.65 set N&T on W side 9" W. pine S68°W 8.05' set N&T S side 18" W. Pine Stump East – West woven wire fence 3' South North – South woven wire fence 8' West

Wit: N62°E 29.80' to set N&T on SE side 3" Maple S06°E 24.16' to set N&T on E side 12" W. Oak S53°W 12.38' to set N&T on SE side 17" W. Oak N34°W 15.48' to set N&T on SW side 11" W. Oak

Set Blue Carsonite post w/location tag 1' North.

Set Blue Carsonite post w/location tag 1' North

Surveyor's Michigan License No.:

33981

CARL
KIISKILA
LAND
SURVEYOR
No.
33981
FO LAND SURVEY

1-23-12

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS JAN. 28, 1971 Revised May 14, 1975

Revised May 14, 1975 Revised Jan. 1983 Revised Oct. 1995