

SURVEY & REMONUMENTATION

Liber 00012 Page 0129

APR 24 1995

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

COMMISSION

For corners in

Montmorency
(County)

Located In:
Briley Township

Corner Code -#

1. Public Land Survey

T 30 N R 2 E

T 30 N R 2 E

T R

T R

S T R

S T R

S T R

S T R

2. Property Controlling in Section

3. Miscellaneous

Property in Sec.

APPROVED BY
PEER GROUP

MAY 13 94

4. Lot No. , Recorded Plat

5. Private Claims

STATE OF MICHIGAN
MONTMORENCY COUNTY
Recorded & Filed

11-10-1994 14:12:38

A. PANGAN-MCELROY
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

I, Don Marlatt, in a field survey on November, 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(D-13) S. $\frac{1}{4}$ Cor. Sec. 32, T 30 N, R 2 E
Post set by Lewis Clawson 1-10-1840.
18" Hemlock N 24° E 67 links
6" W. Pine N 29° W 12 links
D. Porter - Survey, L. 1, P. 280.
D. Porter - Rec. Act 74, L. 1, P. 50.
DNR Survey - Sept. 1977

(E-13) South Cor. common to Secs. 32 & 33, T 30 N, R 2 E
Post set by Lewis Clawson.
6" Aspen N 37° E 12 links
6" Aspen N 63° W 23 links
D. Porter - Survey, L. 1, P. 280.
D. Porter - Rec. Act 74, L. 1, P. 50.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(D-13) S. $\frac{1}{4}$ Cor. Sec. 32, T 30 N, R 2 E
Found $\frac{1}{2}$ " rod & cap by D. Porter.
9" Oak N 12° W 15.66'
8" Oak N 86° E 21.59'
10" Oak S 4° E 32.75'
No evidence of original corner.

(E-13) South Cor. common to Secs. 32 & 33, T 30 N, R 2 E
Found concrete monument.
12" Oak N 75° E 43.45'
24" N. Pine S 70° E 13.01'
24" Oak S 70° W 33.86'
No evidence of original corner.

Accepted as the best available evidence of the reestablishment of the original corner.

Accepted as the best available evidence of the reestablishment of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(D-13) S. $\frac{1}{4}$ Cor. Sec. 32, T 30 N, R 2 E
Placed Remonumentation Cap on $\frac{1}{2}$ " rod.
8" Maple N 65° W 29.24'
12" Maple N 25° W 15.68'
6" Oak N 35° E 6.01'
12" Oak N 89° E 21.75'

(E-13) South Cor. common to Secs. 32 & 33, T 30 N, R 2 E
Placed Remonumentation Cap on concrete monument.
24" R. Pine S 35° E 12.92'
16" R. Pine S 40° W 41.65'
24" Oak S 72° W 33.72'
11" R. Pine N 35° W 11.35'
N.W. Cor. Sec. 4, 29/2, 13.18' East

Witnesses marked with a 30 penny spike & I.D. tag #18660.

Signed by

Donald E. Marlatt

Date

11-9-1994

Surveyor's Michigan License No.

18660

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JANUARY 1993

