

SURVEY &
REMONUMENTATION

APR 24 1995

Montmorency County Remonumentation

Liber 00012 Page 0130

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Montmorency
(County)

Located In:
Briley Township

Corner Code #

1. Public Land Survey

T 30 N R 2 E

F-13 ✓

T 30 N R 2 E

G-13

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

APPROVED BY
PEER GROUP

MAY 13 94

RB

STATE OF MICHIGAN
MONTMORENCY COUNTY
Recorded & Filed

11-10-1994 14:12:49

A. PANGAN-MCELROY
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

I, Don Marlatt, in a field survey on November 8, 19 94,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law, established, re-established, monumented, re-monumented, recovered, found as
expressed below.

NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(F-13) S. $\frac{1}{4}$ Cor. Sec. 33, T 30 N, R 2 E
Post set by Lewis Clawson 1-10-1840.
24" Y. Pine N 44° E 25 links
24" Y. Pine N 69° W 77 links
DNR Survey - Sept. 1977
Ken Ostling - filed Act 74, L. 1, P. 211.
D. Marlatt - 12-15-93, Survey.

(G-13) South Cor. common to Secs. 33 & 34, T 30 N, R 2 E
Post set by Lewis Clawson 1-10-1840.
24" W. Pine N 22° E 25 links
18" W. Pine N 55° W 46 links
D. Porter - filed Act 74, L. 1, P. 63.
DNRI Survey - Sept. 1977
Ken Ostling - Recorded Act 74, L. 1, P. 210.
D. Marlatt - 12-15-93, Survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(F-13) S. $\frac{1}{4}$ Cor. Sec. 33, T 30 N, R 2 E
Found DNR Monument.
6" Maple N 30° E 13.1'
6" W. Oak N 22° W 31.55'
N. $\frac{1}{4}$ Cor. Sec. 4, 29/2, 15.2' East
No evidence of original corner.

Accepted as the best available evidence of the
reestablishment of the original corner.

(G-13) South Cor. common to Secs. 33 & 34, T 30 N, R 2 E
Found concrete monument.
County Road Commission Notes:
Mon. N 45° E 50' -- Mon. N 45° W 50'
Porter's Act 74: 4" Conc. marker N 45° E 50.1'
15" Oak S 15° W 65.9'
24" Oak West 12.68'
Conc. Mon. East 19.14'
4" Conc. Marker S 30° W 53.85'
Ostling's Act 74: 28" Oak West 11.4'
11" R. Pine N 50° W 23.4'
Conc. Mon. N 45° W 50.2'
Conc. Mon. N 45° E 50.1'

No evidence of the original corner.

Accepted as the best available evidence of the
position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(F-13) S. $\frac{1}{4}$ Cor. Sec. 33, T 30 N, R 2 E
DNR Monument.
6" Maple N 30° E 13.10'
6" W. Oak N 22° W 31.55'
8" Oak N 45° W 11.30'
12" Oak North 28.46'
11" Oak N 47° E 34.43'
8" Oak N 73° E 15.53' - N. $\frac{1}{4}$ Cor. Sec. 4, 29/2, 13.18' East.

(G-13) South Cor. common to Secs. 33 & 34, T 30 N, R 2
Placed Remonumentation Cap on concrete monument.
17" Oak S 22° W 66.15'
15" Oak S 60° W 29.32'
26" Oak N 86° W 11.48'
17" N. Pine N 48° W 23.80'
15" N. Pine S 65° E 18.51'
N.E. Cor. Sec. 4, 29/2, 19.1' East.

Signed by Donald E. Marlatt

Date 4-9-1994

Surveyor's Michigan License No. 18660

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28,
REVISED MAY 14,
REVISED JAN.

Witnesses marked with 30 penny spike and I.D. tag #18660.