

Liber 00012 Page 0346

MONTMORENCY COUNTY REMONUMENTATION

SURVEY & SURVEY & Filing Requirement of Act 74, Mich. P.A. 1970

NOV 2 3 1999 For corners in Located In: Montmorency **Briley** Corner Code # SECTION (Township) (County) STATE OF MICHIGAN 1. Public Land Survey T 30N R 2E G-10 MONTMORENCY COUNTY Recorded & Filed 08-10-1999 14:43:33 2. Property Controlling in Section TERESA WALKER 3. Miscellaneous REGISTED STREET A FILE Property in Sec. , Recorded Plat 5. Private Claims c I, Larry G. Beauregard, in a field survey on April, 19.99 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: NOTE: Not more than 2 comers, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: G-10 - 1/4 Cor. 27 & 28, T30N, R2E 1840 - Lewis Clason, D.S. Set Qr. Sec. Post. (Wit's mkd.) (W. Pine 12" N51E 26 lks) (Y. Pine 8" S38 25 lks). 1977 - Kenneth J. Ostling, RLS #10068, DNR Surveyor. Set corner by proportionate measurement, midpoint on line, between Section Corners while making a Retracement Survey of Sec. 27. Cor. Falls in center line of N. & S. Road. 1978 - Filed LCRC, Rec. L. 1, Pg. 209. Wit's mkd. (8" Maple N65°W 50.8') (11" Maple S48°W 64.3) (Cedar Post West 36'). See copy of map in dossier. Description of corner evidence found and/or method applied in restoring or reestablishing corner: April, 1999 - Fnd. DNR 1" pipe, no cap, in center line of Co. Rd. #489. Pipe had been hit and was bent over. Replaced pipe with a 4" dia. X 36" conc. Mon. and Re-mon. Cap, set 6" below Rd. surface on a line with S 1/8th Cor. and SE Cor. Sec. 28 at double the distance measured between S. 1/8th Cor. and Sec. Cor. Description of monument for corner and accessories established to perpetuate locating the position of the corner: G-10 - 1/4 Cor. 27 & 28, T30N, R2E 3 1/4" Aluminum Re-mon. cap on 4" dia, X 36" concrete monument. APPROVED BY Accepted as the best available evidence of the re-establishment of the original corner. PEER GROUP Approved by the Peer Group on July 20, 1999. JUL 2 0 99 N56°W 50.89' 10" Maple (Ex. blaze) (Placed 60d Spike & P.S. Tag 18654) N42°W 60.80 8" W. Pine 9" W. Pine NAUMN 60.80 N50°E 50.15 P. Pole (Placed Pk. Nall & P.S. Tag18654) N85°W Red Top Post & Location Tab.

Farry G. Brauregard

Signed by _

Surveyor's Michigan License No.

August 5, 1999

Date.