

SURVEY & REMONUMENTATION

JAN 22 2001

Montmorency County Remonumentation

Liber 00012 Page 0433

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

MONTMORENCY

Located In:

Corner Code #

(County)

BRILEY TWP.

1. Public Land Survey

T30N R 2E

B-1

T R

T R

T R

T R

2. Property Controlling
in Section

S

T R

3. Miscellaneous
Property in Sec.

S

T R

S

T R

STATE OF MICHIGAN
MONTMORENCY COUNTY
Recorded & Filed

12-05-2000 10:03:00

TERESA WALKER
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L	
1													
2	6		5			4		3		2		1	
3													
4	7		8			9		10		11		12	
5													
6	18		17			16		15		14		13	
7													
8	19		20			21		22		23		24	
9													
10	30		29			28		27		26		25	
11													
12	31		32			33		34		35		36	
13													

I, DONALD E MARLATT, in a field survey on MAY, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

B-1 N. 1/4 COR. OF SEC. 6 (NO CORNER SET IN ORIGINAL SURVEY)

G.G. SLATTERY P.E. M.S.H.D. SURVEY CREW CHIEF SET 1 1/4" PIPE ON LINE BY G.L.O. PROPORTION.

S15°W 28.05' 10" MAPLE, N80°E 27.53' 10" MAPLE, S62°W 31.6' 14" MAPLE.

COUNTY ROAD COMMISSION NOTES (NO DATE) 1 1/4" PIPE. WITNESSES SAME AS ABOVE.

D.E. MARLATT P.S. #18660. ACT 132 4/30/80 RECORDED IN LIBER 3, PAGE 28 FD. 1 1/4" PIPE.

S15°W 28.05' 10" MAPLE, N80°E 27.53' 13" MAPLE, S62°W 31.6' 16" MAPLE.

D.E. MARLATT P.S. ACT 132 4/30/80 REC. L.3, P. 26. (WIT. & COR. SAME AS ABOVE).

D.E. MARLATT P.S. ACT 132 4/30/80 REC. L. 3, P. 27. (WIT. & COR. SAME AS ABOVE).

J.L. SCHWANDT P.S. #26466 ACT 132. 9/3/99. REC. IN L. 10005, P. 125. (WIT. & COR. SAME AS ABOVE).

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

B-1 N. 1/4 COR. OF SEC. 6

FOUND 1 1/4" PIPE

S20°W 14" MAPLE 27.45' R.

S64°W 16" MAPLE 31.58' R.

APPROVED BY
PEER GROUP

JUL 18 00

L.L.B.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

B-1 N. 1/4 COR. SEC. 6

SET CONC. MONUMENT & REMON. CAP.

S24°E P. POLE 2.03'

S28°E 12" HEMLOCK 26.60'


S20°W 14" MAPLE 27.45'

N71°W 11" W. PINE 24.60'

S64°W 16" MAPLE 31.58'

WITNESSES MARKED WITH 40 PENNY SPIKES & P.S. TAGS # 18660.

APPROVED BY PEER GROUP JULY 18, 2000 AS A CAREFUL AND FAITHFUL ESTABLISHMENT OF THE POSITION OF THE CORNER.



Signed by Donald E Marlatt

Date 12/4/2000

Surveyor's Michigan License No. 18660