

# REMONUMENTATION

## Montmorency County Remonumentation

### LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

APR 24 1995

Liber 00012 Page 0071

For corners in

MONTMORENCY COMMISSION

Located in:  
HILLMAN TWP.

Corner Code #

1. Public Land Survey

T 31N R 4E B-1

APPROVED BY  
PEER GROUP

2. Property Controlling  
In Section

S T R

3. Miscellaneous  
Property in Sec.

S T R

AUG 05 94

STATE OF MICHIGAN  
MONTMORENCY COUNTY  
Recorded & Filed

10-19-1994 13:48:13

Register of Deeds Stamp & File Number  
H. PANGAN-MCELROY  
REGISTER OF DEEDS

1. Lot No. Recorded Plat

2. Private Claims

FREDERICK J. KING, in a field survey on July 29, 1994

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as pressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

1. North 1/4 Corner, Section 6, T.31 N., R.4 E.,

July 1855 - Original Post set by Butler Ives, D.S. S42W - Blk Oak - 9.24' (1411k\$)  
N39W - W Pine - 17.82' (2711k\$)

Oct. 1984 - Act #74 Rec Bk 1, Pg 357 S35E - 4" Maple - 18.35'  
3/4" Pipe fnd by L.G. Beauregard, PS S35W - 5" R Oak - 14.83'  
#18654 - Set by Unknown Surveyor N40W - 4" r Oak - 14.80'

NO ACT # 132 FOUND RECORDED, FOR THIS CORNER

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

North 1/4 Corner, Section 6, T.31 N., R.4 E.,

7-29-94 - Fnd Rec 3/4" Pipe - S20°E. (R-S35E) - 18.35' - Fnd Spk in Maple  
S80°W. (R-S35W) - 14.78' (R-14.83') - Fnd Spk in R Oak  
N40°W. - 14.72' (R-14.80') - Fnd Spk in R Oak

No 1855 Wit Fnd.

This Corner Approved by County Peer Review on August 5, 1994, as the best available evidence of the position of the Original Corner

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

North 1/4 Corner, Section 6, T.31 N., R.4 E.,

7-29-94 - Set 1/2" Re-Rod & Co Re-Mon Cap on N. Side of Fnd Pipe  
Placed Treated 2"x4" on S. Side  
East - ± 4 1/2' - N-S Fence Wire  
South - ± 3' - E-W Fence Wire  
N30°E - 31.79' - Set Tag in NW Sd 27" R Pine  
S20°E - 18.35' - Set Tag above Fnd Spk - 6" Maple  
S80°W - 14.78' - Set Tag above Fnd Spk - 6" R.Oak  
N40°W - 14.72' - Set Tag above Fnd Spk - 6" R Oak



by Frederick J. King

Date 10-18-94

Surveyor's Michigan License No. 25852