

MAY 1 8 1987

COMMISSION

Montmorency County Remonumentation

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

Liber 00012 Page 0206

For corners in

MONTMORENCY

(County)

HILLMAN TWP.

1. Public Land Survey

Located In:

Corner Code ##

T 31N R 4E

C - 13

T R

T R

T R

2. Property Controlling  
in Section

S T R

S T R

3. Miscellaneous

S T R

Property in Sec.

S T R

STATE OF MICHIGAN  
MONTMORENCY COUNTY  
Recorded & Filed

11-01-1996 09:41:57

A. FANGAN-MCELROY  
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

I, DONALD E MARLATT, in a field survey on 7-1, 19 96,  
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned  
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the  
current manual of survey instructions of the United States Department of the Interior, Bureau of Land  
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5  
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a  
Court of Law; established, re-established, monumented, re-monumented, recovered, found as  
expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded  
on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

C - 13 SOUTH CORNER COMMON TO SEC'S 31 & 32

CORNER SET BY LEWIS CLASON 3-18- 1839.

CEDAR 9"-N12E-58

ACT 74 BY KEN OSTLING L. 1, P. 326, 847-82, SET CABIN SPIKE IN CEDAR STP. BY S.P. METHOD.

DNR SURVEY 8-1982. 14"CEDAR S35°E 3.25'- 12"CEDAR S75°W 4.5'. SURVEY REPORT ON FILE.

D.E. MARLATT SURVEY 6-1-86, L. 3, P. 356, FOUND CABIN SPIKE & WIT. ABOVE.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

C - 13 SOUTH CORNER COMMON TO SEC'S 31 & 32

FOUND CABIN SPIKE IN CEDAR STP

S35°E 3.25' 14"CEDAR - S75°W 4.5' 12"CEDAR

NORTH 1/4 COR. SEC. 5, T30N, R4E IS 83.45' WEST.  
NO EVIDENCE OF ORIGINAL CORNER

APPROVED BY  
PEER GROUP

JUL 12 96

J.M.B.

NOTE: MSHD SURVEY DATED 4-5-1966 WAS NOT ACCEPTED FOR CORNER POSITION.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C - 13 SOUTH CORNER COMMON TO SEC'S 31 & 32, T31N, R4E

DROVE 1/2" RE BAR IN STUMP AND PLACE REMON CAP.

S35°E 14"CEDAR 3.25'

S75°W 12"CEDAR 4.5'

N40°W 14"CEDAR 20.45'

N45°E 12"CEDAR 11.17'

WITNESSES MARKED WITH 30 PENNY SPIKES AND P.S. TAGS #18660  
APPROVED BY PEER GROUP JULY 12, 1996 AS THE BEST AVAILABLE EVIDENCE  
OF THE POSITION OF THE ORIGINAL CORNER.



Signed by

Donald E Marlatt

Date

10/28/96

Surveyor's Michigan License No.

18660