## SURVEY & REMONUMENTATION

## Montmorency County Remonumentation Liber 00012 Page 0141

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, REVISED MAY 14, REVISED JAN.,

APR 2 4 1995

## LAND CORNER RECORDATION CERTIFICATE

Eor	Filing Requirement of Act 74, Mich. P	P.A. 1970
	Montmorency Township  Corner Code ##	STATE OF MICHIGAN MONTMORENCY COUNTY
1.	Public Land Survey T 32 N R 3 E A-1	Recorded & Filed
	T R APPROVED BY	11-10-1994 14:15:09
	T R PEER GROUP  Property Controlling S T R	A. PANGAN-MCELROY REGISTER OF DEEDS Register of Deeds Stamp & File Number
4.	Lot No, Recorded Plat	A B C D E F G H I J K L
5.	Private Claims	2 6 5 4 3 2
		3
, [	Oon Marlatt , in a field survey on November 8 , 19 94	1 7 - 1 8 - 1 9 - 1 10 - 1 1 1 - 1 2 5 1 1 1 1 1 1 1 1 1 1 1 1 1
in li curi Mar abo Cou exp	nereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points ment ness 1 and 2 above were in conformance with regulations and rules therefore as required rent manual of survey instructions of the United States Department of the Interior, Bureau of pagement or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 we were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decret of Law; established, re-established, monumented, re-monumented, recovered, four ressed below:	tioned in the function of the
NO	TE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.	11 12 31 32 33 34 35 36
		13 13 13 13 13 13 13 13 13 13 13 13 13 1
A. (A-1)	Description of original monument and accessories and/or subsequent restoration N.W. Cor. Sec. 6, T 32 N, R 3 E Original post set by Hiram Burnham July, 1850. 14" Y. Pine S 47° W 23 links 12" Y. Pine N 5° E 9 links	<b>.</b>
	Schaaf - DNR - No Date.	
B. (A-1)	D. Porter - Recorded Act 74, L. 1, P. 398 on June 22, 1987.  Description of corner evidence found and/or method applied in restoring or rees  N.W. Cor. Sec. 6, T 32 N, R 3 E  Found 2" pipe in concrete (concrete broken).  16" Oak 5 85° W 77.45' Ex. blaze (Porter)	tablishing corner:
	16" Oak N 23° W 55.03' Ex. spike.	
	No evidence of original corner.	
	Accepted as the best available evidence of the position of the original	al corner.
C.	Description of monument for corner and accessories established to perpetuate le	ocating the position of the corner:
(A-1)	N.W. Cor. Sec. 6, T 32 N, R 3 E Set concrete monument & Remonumentation Cep. 16" Oak S 85° W 77.45' 8" J. Pine S 10° E 42.8' 15" Oak S 54° E 30.15' 16" Oak N 85° E 47.47' 16" Oak N 23° W 55.03' Witnesses marked with a 30 penny spike & I.D. tag #18660.	DONALD E. MARLATT SURVEYOR NO. 18660
Sig	ned by Nonaid E Market Date	11-9-1994

18660

Surveyor's Michigan License No. .