

1993 NEWAYGO COUNTY REMONUMENTATION PROJECT
NEWAYGO COUNTY
REGISTER OF DEEDS
MARLENE TOOGOOD

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

'94 JAN 21 PM 3 24

For corners in

NEWAYGO

(County)

Located in:

Corner Code #

1. Public Land Survey

T 11N R 12W

C-3

T R

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

4. Lot No. , Recorded Plat

5. Private Claims

VOL 001 PAGE 06

Register of Deeds Stamp & File Number

I, Norman L. Ochs, in a field survey on December 4, 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

SW Corner, Section 5, Grant Twp.

A. Description of original monument and accessories and/or subsequent restoration:

G.L.O. 1838

NCRC Sheet

J.H. Mullett

3/4" Rod

8" Spruce S61°W 11 lks #1

P Pole S52°W 70.2' #5

8" Tamarack N14°W 11 lks #2

10" Maple N46°E 79.4' #6

10" Maple N27°W 47.1' #7

W. S. Merrill 9-30-1888

6" Spruce S25°W 70 lks #3

7" Pine S60°E 1.11-1/2 lks #4

Book A pg's 103 & 104

Measured 39.86 chains to South (2630.76')

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 5/8" Bolt 1.5' West of N&S Road and 2.0 ft South of E&W road.

Set 4" Harrison cast iron monument.

Condition of recorded witnesses is #1 thru #4 gone, #5 & #6 good condition, #7 gone, #8 good condition.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Accepted 4" Harrison cast iron monument as a substantial marker for the section corner and is accepted as a careful and faithful re-establishment of the original corner.

P. Pole S50°W 70.45' Spike in SE side of pole #5.

16" Maple N48°E 79.97' Spike in Southeasterly side of tree #6.

10" Maple S23°E 75.32' Spike in East side of tree #8.

10" Elm N15°E 140.48' Spike in West side of tree.



Signed by Norman L. Ochs

Date December 15, 1993

Surveyor's Michigan License No. 22439

Approved by Peer Review Group December 27, 1993

Norman L. Ochs, County Representative

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 26, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983

SURVEY &
REMONUMENTATION

DEC 07 2000

SECTION