

MAR 0 2 1999

SECTION

1998 Newaygo County Remonumentation Project REGISTER OF DEEDS

NEWAYGO COUNTY REGISTER OF DEEDS LINDA M. BROWN

LAND CORNER RECORDATION CERTIFICATE
FILING REQUIREMENT of Act 74, Mich. P.A. 1970 '99 FEB 17

99 FFR 17 PM 3 42

For corners in Newaygo (County)	Located in:	Corner Code #	Linsa III	. Brown
Public Land Survey	T <u>14N</u> R <u>12W</u> T R T R	L-13	vol. 2	263
Property Controlling in Section Miscellaneous Property in Sec.	STR STR STR STR		Register of Deeds_Stamp & l	File_Number
do hereby certify that under req points mentioned in lines 1 and therefore as required in the cur Department of the Interior, Bure Law and/or that the corner po conformance with the rules of	, in a field survey on October 26 uirements of P. A. 74, Michigan P.A. of 19 2 above were in conformance with regulation of the cent manual of survey instructions of the cent manual of Management or by a decree oints mentioned in lines 3, 4 and 5 about the Michigan Board of Land Survey olished, re-established, monumented, re-	70, the corner ons and rules United States of a Court of over were in ors or by a	A B C D E F G H 2 - 6 - 5 - 4 - 3 3 - 1 - 1 - 16 5 - 18 - 17 - 16 - 15 7 - 19 - 20 - 21 - 22 9 - 1 - 1 - 22	11 - 12 -
Note: Not more than 4 recorded on this	corners, all in the same town a certificate.	nd range, may be	$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$	1-1-1-1
South One Quarter Corner,	Section 36, Everett Township, Neway	ygo County, Michigan		لهُلتَل

A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

G.L.O. John Hodgson 1837 14" Tamarack S17°E 28 Links (18.48')#1 6" Pine N50°W 26 Links (17.16')#2

Lyle S. Shepherd R.L.S. #503 Witness Book Number 1, Page 17 15" Black Oak 71.7' #3 6" Elm N20°W 20.2' #4 Corner Post S07°W 32.2' #5 Lyle S. Shepherd R.L.S. #503
Book 81, Page 45 October 5, 1934
Measured 2651.5 feet from the South One Quarter Corner to the Southeast Corner of Section 36.

Norman L. Ochs R.L.S. #22439
July 31, 1980 Set ½" Rod and Cap
8" - 12" Twin Maple S10°W 57.98' #6
8" - 6" Twin Maple S60°E 69.65' #7
12" - 6" Twin Maple N21°E 79.21' #8

North One Quarter Corner, Section 1, T13N R12W, West 6.60' #9

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found ½" X 19" Rerod with cap (illegible, Rerod driven thru cap). The centerline of the East and West bituminous road is 1.5 feet ± North and there is no apparent occupation going North. The condition of the recorded witnesses are: #1 thru #5 gone, #6 stump, #7 thru #9 good condition.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Removed Rerod and set a 2¾" X 20" Harrison cast iron monument marked "County Survey" in a new 8" diameter monument box as a substantial marker for the section corner and is accepted as a careful and faithful reestablishment of the original corner.

the original corner.			annaman.
6" - 12" Twin Stump S06°W 57.6'± to centerline. #6 8" - 14" Twin Maple (blazed) S65°E 69.95' Found spike in S 8" - 14" Twin Maple (blazed) N17°E 79.23' Found spike in V	Nesterly side		NORMAN L: OCHS
North One Quarter Corner, Section 1, T13N R12W, West 6			LAND X
16" Elm (blazed) S08°W 63.33' Found spike in West side o			Z → SURVEYOR =
Power Pole N75°W 134.62' Set spike with tag #22439 in No	ortheasterly	side of pole.	No. 10
Signed by Morman L. Ochs	Date	November 3, 1998	22439
Norman L. Ochs			WHAT I AR DELLE
Surveyor's Michigan License No. 22439	Form appro	oved by Michigan State Board	of Land Surveyors, Jan 28, 1971
Approved by Peer Review Group on			Revised May 14, 1975 Revised Jan., 1983