SURVEY & REMONUMENTATION

118FR 15288 PG 517 TO

Mar 1095040431

MAY - 1 1995

\$ 7.00 HISC RECORDING CHG - IN HOUSE

\$ 2.00 REMON CHG - IN HOUSE

	COMMISSION
CATHORS	in

County

Public Land Survey

2. Property Controlling

Miscellaneous

Property in Sec.

in Section

LAND CORNER RECORDATION CERTIFICATED HAR 95 4:03 P.M. Filing Requirement of Act 74, Mich. P.A. 1970

RECEIPT# 1778 RECORDED - DAKLAND COUNTY

LYNN D. ALLEN, CLERK/REGISTER OF DEEDS

Oakland

Commerce Twp. Corner Code ## Located In: T 2N_ R 8E_ A-1 T ____ R __ _. R _ _ R T Τ... R _ T _ _ R _

OK - T. SMITH

Compliance with ACT 345, P.A. 199 12-27-9

APPROVED ON OAKLAND COUNTY REMONUMENTATION PEER GROUP COMMITTEE

Register of Deeds Stamp & File Number

Lot No, Recorded Plat Private Claims

_ T .___ R _

T

David Pawlaczyk , in a field survey on . December 15 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

1815 п/а	Post Iron pipe	G.L.O. Field	A. Holmes	n/a	Notes
Ha	non pipe	notes	M. Baldwin	n/a	Oakland County Records
1978	1/2" Re-rod	L.C.R.C.	A. Leach	#7236	L7298 P131
	1/2" Re-rod	L.C.R.C.	A. Leach	#7236	L7298 P132
	1/2" Re-rod		A. Leach	#7236	L7298 P133

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A 1/2" iron rod in a gravel road currently occupies this corner. The following witness ties were used to recover and verify its position:

2 ties from M. Baldwin witnesses

2 ties from L.C.R.C. L7298 P131-133

Field measurements were made between the following corners:

A-1 to B-1 2865.83 meas. **Oakland County Planning** 2866.09 Property desc. rec. 2780.08 meas. A-1 to A-2 L174 P22 2780.12 plats rec.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I placed a 2" diameter brass cap stamped "Oakland County Remonumentation P.S. #17632" on the existing 1/2" iron rod in a gravel road. OF MICHIO

N.72° E. 61.79 S.60° E. 81.18

P.K. nail and O.C.R. tag in S.E. face 6" Elm P.K. nail and O.C.R. tag in N. face D.E. pole

S.12° E. 47.10 N.E. corner stone house

s.39° W. 52.43' N.W. corner stone house

N.42° W. 42,14'

P.K. nail and O.C.R. tag in N. face D.E. pole

The selected location is accepted by me and generally accepted by Professional Surveyors as the being evidence of the position of the original corner.

Signed by

2-16-95 __ Date __

> FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAH. 28, 1971 REVISED MAY 14, 1975

REVISED JAN., 1983

Surveyor's Michigan License No. ___17632

2.00

DAVID

PAWLACZYK

LAND SURVEYOR NO

2.00