

SURVEY & REMONUMENTATION

MAY - 1 1995

COMMISSION

For corners in Oakland

(County)

Located In:

Corner Code ##

- | | | |
|------------------------------------|---|-------------|
| 1. Public Land Survey | T <u>2N</u> R <u>8E</u> | <u>I-1</u> |
| | T <u> </u> R <u> </u> | <u> </u> |
| | T <u> </u> R <u> </u> | <u> </u> |
| | T <u> </u> R <u> </u> | <u> </u> |
| 2. Property Controlling in Section | S <u> </u> T <u> </u> R <u> </u> | <u> </u> |
| | S <u> </u> T <u> </u> R <u> </u> | <u> </u> |
| 3. Miscellaneous | S <u> </u> T <u> </u> R <u> </u> | <u> </u> |
| Property in Sec. | S <u> </u> T <u> </u> R <u> </u> | <u> </u> |

4. Lot No. , Recorded Plat
5. Private Claims

I, David Pawlaczyk, in a field survey on December 21, 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

No L.C.R.C. has ever been recorded for this corner. Original government land office notes indicate a post never being set at this point but a falling indicated as being west 205.92' from the S.W. corner of Section 35, T-3-N., R-8-E. No L.C.R.C. has ever been recorded for I-13 of T-3-N., R-8-E.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A 3/4" pipe in an existing monument box in asphalt pavement at the intersection of Carroll Lake Road and Cooley Lake Road currently occupies this corner. Field measurements were made between the following corners:

I-1 to H-1	2619.92	meas.		
I-1 to I-2	2886.45	meas.		
	2737.68	rec.	G.L.O.	Notes
	2885.17	rec.	Plats	L26 P4

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I replaced the 3/4" pipe with a 5/8" x 24" iron rod with a 2" diameter brass cap stamped "Oakland County Remonumentation P.S. #17632" in an existing monument box.

N.72° E.	85.49'	P.K. nail and O.C.R. tag in S.E. face D.E. pole
S.29° E.	119.08'	P.K. nail and O.C.R. tag in N.E. face clump trees
S.41° W.	67.33'	P.K. nail and O.C.R. tag S.E. face utility pole
N.71° W.	88.49'	P.K. nail and O.C.R. tag S. face D.E. pole

The selected location is accepted by me and generally accepted by Professional Surveyors as the best available evidence of the position of the original corner.

Signed by [Signature] Date 2-16-95

Surveyor's Michigan License No. 17632

MAR 10 95 040422

LIBER 15288 PG 508

\$ 7.00 MISC RECORDING CHG - IN HOUSE
\$ 2.00 REMON CHG - IN HOUSE
10 MAR 95 4:01 P.M. RECEIPT# 1778
PAID RECORDED - OAKLAND COUNTY
LYNN D. ALLEN, CLERK/REGISTER OF DEEDS

Compliance with
ACT 345, P.A. 1990

APPROVED ON: 12-27-94
OAKLAND COUNTY REMONUMENTATION
PEER GROUP COMMITTEE

OK - T. SMITH

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

