

LIBER 19548PG777

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in:

Oakland County

Located In: Corner Code #
West Bloomfield Township

1. Public Land Survey

2. Property Controlling
in Section

3. Miscellaneous
Property in Sec.

4. Lot No. _____ Recorded Plat _____
5. Private Claims _____

T2N R9E D-11
T R
T R
T R
S T R
S T R
S T R
S T R

SECTION

\$ 9.00 MISCELLANEOUS RECORDING
\$ 2.00 REMONUMENTATION
11 FEB 99 9:01 A.M. RECEIPT # 34
PAID RECORDED - OAKLAND COUNTY
G. WILLIAM CADDELL
CLERK/REGISTER OF DEEDS

Compliance with
ACT 345, P.A. 1990

APPROVED ON: 2-3-99 JS
OAKLAND COUNTY REMONUMENTATION
PEER GROUP COMMITTEE

Register of Deeds Stamp & File Number

I, Huston K. Kennedy, in a field survey on October 21, 1998 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:
1817-GLO Carpenter, D.S.; Set Post 18" Hickory N72°E 4 1/4 Links; 4" Red Budd S76 1/2° W 24 Links;
1.) 1973-Carlson, PS #14759; LCRC L.6229, Pg.749 - Set a PK Nail
2.) 1973-Crossman, PS #9428; LCRC L.6097, PG.561 - Fnd a PK Nail
3.) 1994-Wozniak, PS #15088; LRC L.14709, Pg.321 - Fnd a Iron Bar in a well
4.) 1984-Giffels-Webster Engineers, Inc., Unrecorded Survey - Fnd Iron found in a handhole, no witnesses
5.) 1987-Zemet-Wozniak & Associates, Inc., Unrecorded Survey - Object found not stated no witnesses
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
1998-Kennedy Surveying, Inc. - Kennedy, PS #17623 - Fnd a 5/8" Iron Rod in a Monument Box located in the center turn lane for of Maple Road extending to the East & West, which has a bituminous surface, also 60 feet West of the entrance to Henry Ford Medical Center to the South, which has a bituminous surface.

Witnesses from LCRC #1, 2 & 3 were used to recover and verify the location of the found 5/8" Iron Rod in a Monument B
I accepted the found 5/8" Iron Rod in a Monument Box as the best evidence of the original corner position.

FIELD MEASUREMENTS BETWEEN

D-11 to C-11

GLO = 39.91 chains or 2634.06 Ft.
Sidwell W 1/2 of Sec 28 (18-29) = 2661.32 Ft.
Sidwell W 1/2 of Sec 32 (18-32) = 2662.29 Ft.
2661.57 Ft. (GPS-MEA)

Cont on back side of LCRC

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
D-11 I replaced the found 5/8" Iron Rod with a 5/8" x 24" Iron Rod w/2" diameter brass cap stamped Oakland County
Remonumentation, PS #17623 in a existing Monument Box
N63°W 172.62' Cut "x" top of bolt on Fire Hydrant
N04°E 50.46' Set Mag Nail & Remon Washer East face Power Pole North 33.03 feet found 1/2" Iron Rod
N57°E 130.88' Set Mag Nail & Remon Washer SE face Guide Pole South 60.06 feet found 4" dia. Concrete Monument
S20°E 59.09' Cut "x" on top of a bolt in a concrete base on the NW side of Traffic Pole

The selected location is accepted by me and is generally accepted by Professional Surveyors as the best available evidence of the position of the original corner.

Signed by: Huston K. Kennedy

Surveyor's Michigan License No. 7623

Date 2-5-99

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 1998
REVISED MAY 1998
REVISED JAN 2000
REVISED OCT 2000

