

COPY

LIBER 18742 PG 836

98 217415

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Oakland  
(County)

Located in: Corner Code #  
West Bloomfield Township

1. Public Land Survey

T2N R9E J-5

2. Property Controlling  
in Section

S T R

3. Miscellaneous  
Property in Sec.

S T R  
S T R  
S T R

4. Lot No. Recorded Plat

5. Private Claims

SECTION 5  
bloomfield

\$ 7.00 MISCELLANEOUS RECORDING  
\$ 2.00 REMONUMENTATION  
23 JUL 98 10:53 A.M. RECEIPT# 1764  
PAID RECORDED - OAKLAND COUNTY  
LYNN D. ALLEN, CLERK/REGISTER OF DEEDS

Compliance with  
ACT 345, P.A. 1990

APPROVED ON: 6-30-98 JS  
OAKLAND COUNTY REMONUMENTATION  
PEER GROUP COMMITTEE

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Huston K. Kennedy, in a field survey on April 24, 1998 hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:  
1817-GLO Carpenter, D.S.; No post was set, corner falls in a lake.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:  
1998-Kennedy Surveying, Inc. - Kennedy, PS #17623 - The corner has not been perpetuated, the corner falls in Pine Lake.

HOW THE CORNER WAS RECOVERED

The corner is shown on "SUPERVISOR'S PLAT NO. 8" a plat recorded in Liber 53 of plats, on page 55 of Oakland Cour Records. I set a meander corner on the line between Sections 11 & 14 at the intersection Northwestern line of Lot 28 of se "SUPERVISOR'S PLAT NO. 8".

FIELD MEASUREMENTS BETWEEN

J-5 to I-5

No GLO, corner falls in Pine Lake

J-5 to K-5

No GLO, corner falls in Pine Lake  
2727.59 Ft. (GPS-MEA)

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:  
J-5 I set a 4" diameter Concrete Monument with 1/2" Iron Rod w/2" diameter brass cap stamped Oakland County  
Remonumentation, PS #17623 as a meander corner to J-5  
N25°E 173.94' Set Mag Nail & Remon Washer SE face Power Pole  
S57°E 10.41' Set Mag Nail & Remon Washer NE face Power Pole  
S17°W 165.69' Set Mag Nail & Remon Washer West face Power Pole  
S80°W 67.03' Set Mag Nail & Remon Washer South face Power Pole  
N88°E 637.81 feet, J-5 (Inaccessible corner)

The selected location is accepted by me and is generally accepted by Professional Surveyors as a meander corner the position the original corner based upon "SUPERVISOR'S PLAT NO. 8".

Signed by:

Surveyor's Michigan License No. 17623

Date 7-2-98

