MAY 24 2000

LIBER 21146 - 060 -

LAND CORNER RECORDATION CERTIFICATE

SECTION

	1	Filing Requirement of Act	74, Mich. P.A. 1970	LIBER \$9.00	211 MISC	46 PA	GE EDINO	60				
Fo	or corners in	•	1	\$2,00 02/29	REMO ZODO	NUMENT	ATION 1227 A.	M. R	ECEIP	<b>7# 1</b> 6	5518	
	Oakland (county)	Located In: Corner Code # Waterford Township		PAID G. WI	RE LLIAM	CORDEI CADDI	) - CAP	ERK/F	EGIST	ER OF	F DEI	Ē
2.	Public Land Survey  Property Controlling S in Section S Miscellaneous S	Compliance with ACT 345, P.A. 1996  2.23 200  PROVED ON: PERR CROSS STAND STAND COUNTY REMONSESSIVE TO PERR CROSS STAMP & File Number										
<b>J</b> .	Miscellaneous S Property in Sec. S	T R										
		rded Plat		۾ ڪ	B	с <u>в</u>	E F	, -G	<u>н ।</u>	<del></del>	κ ι Τ	Ţ
	<del></del>	,	<del></del> -	2	- в (	5-	11	1	3	-2 	İ	
1, 5	Joseph C. Kapelczak, in a field s	survey on <u>April 1, 1999,</u> do hereby certify to the comer points mentioned in lines.	hat under requirements	3							L	Į
CO	nformance with regulations ar	nd rules therefore as required in the cui	ment manual of survey	/ K	Ĺ							ĺ
ins	structions of the United States	Department of the Interior, Bureau of Lan	nd Management or by a A and 5 above were in	8	.18		18			_14_		] 13
ÇO	decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of						4			1	1	1
	Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:				-1 <b>9</b> -	20-			12		<b>_</b> ;	Į.
De				9	1		+	_	-	+	∔_	Ŧ
	Description of entrined areas			10	-30	29		;	<u>}</u>	_2j6	<del> </del>	2
A.	Description of original moni	ument and accessories and/or subsec	quent restoration.	11	_	<b>├</b> -╈-		-	╁┼	+-	+-	╁
	Set post in 1816 G.L.O. Su			12	-31	32	33		4	-35	4-	į
	There are no LCRC's recor	ded at Oakland County.		13							1_	1
В.	·	nce found and/or method applied in re										
	between C-11 and E-11 and corner of Parcel #13-32-10	at this location; this corner falls within a d on line with E-11 and an 1/8th corne 0-34. A monument was not placed at set on the north/south 1/4 line between	er between E-11 and t the corner as it falls	D-11 withi	; sai n the	id cor e ceni	ner be ter of a	eing t er or	he so en d	outhy rain.	vest A	
C.	Description of monument for corner and accessories established to perpetuate locating the position of the corner:											
	Set concrete reference mo	nument with OCRT #24598, S 02°44'	30"E 30.00' from D-1	1 wh	ich l	ocatio	n falls	in a	n ope	n dr	ain.	
	Set Witnesses to reference	e monument 30.00' south of D-11:		, .								
	S 89°56'E 10.57' Mag nail v N 11°12'W 75.50' Mag nail	h OCRT #24598 southwest side 28" N with OCRT #24598 in northeast side 2 with OCRT #24598 south side 40" Ma with OCRT #24598 south side 26" Oa	26" Maple. aple.						,	Zp N		
					and the same	RANGE ATE	ostania OF M	CHIO	in <sub>dele</sub>	à.		

Surveyor's Michigan License No. 24598

M APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983