

## UBER 168741117

# LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

	Filing Requirement of Act 74, Mich. P.A. 1	19/U
For corners in	1	\$ 9.00 MISCELLANEOUS RECORDING
Oakland	Located In: Orion TwRcomer Code #	\$ 2.00 REMONUNENTATION
(County)	·	3 JAN 97 7:45 A.M. RECEIPT# 7B PAID RECORDED - DAKLAND COUNTY
1. Public Land Survey	T_4N R_10EI-6 TR TR	LYNN D. ALLEN, CLERK/REGISTER OF DEEDS  Compliance with
2. Property Controlling in Section	STR	APPROVED ON 12.17-94 TS  OTHER CLOCK CHEMISTER.
3. Miscellaneous Property in Sec.	s T R	Register of Deeds Stamp & File Number
Huston K. Kennedy requirements of P.A. 74, Michiconformance with regulations at United States Department of the that the corner points mentions Board of Land Surveyors or recovered, found as expressed NOTE: Not more than 2 con this certificate.	, in a field survey on	The state of the s
D. Daviding of county	evidence found and/or method applied in restoring or reestablishing	corner:
	Grociica idania di	
See back side of LCRC	· See St. L. Section St. St. St.	
	SURVEY & REMONUMENTATION	<b>k</b>
	MAY 2 2 1997	q JD FILE
•	COMMISSION	$\iota$
C. Description of monum	ent for corner and accessories established to perpetuate locating th	e position of the corner:
NO2'E 439.06' Se ( N13'E 195.60' Set N22'E 123.03' Set Due East 270.70'	er Concrete Monument w/2" diameter brass cap stamped Oakland corner of house #515 PK & Remon Washer NW face 12" Apple PK & Remon Washer NW face 12" Apple Pace of steel fence post	HUSTON KENNEDY PROFESSIONAL SURVEYOR 17623
The selected location position of the origin	is accepted by me and is generally accepted by Professiona nal corner.	I Surveyors as the best available evidence
Signed by	Date_	12-18-96
Surveyor's Michigan Lice	nse No. 17 <del>0</del> 23	



### 11968 16874 PG 118

1996 Kennedy Surveying, Inc. - Kennedy, PS #17623 - Fnd The corner as recovered falls in Lot 12 of "SUPERVISOR'S PLAT OF "RE JONES SUBDIVISION", a plat recorded in Liber 53 of plats, on page 51 of Oakland County Records. There are no lines of occupation extending from the recovered corner.

#### FIELD MEASUREMENTS BETWEEN

I-6 to I-5 GLO = 40 chains or 2640.00 Ft., 2785.39 Ft. (MEA 1996) I-6 to I-7 GLO = 40 chains or 2640.00 Ft., 2785.38 Ft. (MEA 1996)

#### LCRC AND RECORDED SURVEYS

Researching the Oakland County Records for Land Corner Recordation Certificates (LCRC) and Certificates of Survey shows that nothing has been recorded for this corner. I did not received any information regarding this corner from letters mailed to other sources.

#### HOW THE CORNER WAS RECOVERED

The corner was recovered at the midpoint between I-5 and I-7, but not on a straight line. The corner was recovered on a projection of the line between block 09-15-100 & 09-15-226 to the midpoint distance of 2785.39 feet from I-5.

SURVEY &
REMONUMENTATION

MAY 2 2 1997

COMMISSION