

**SURVEY &  
REMONUMENTATION**

LIBER 15225 PG 658

JAN 27 1995 016444

MAY - 1 1995

**LAND CORNER RECORDATION CERTIFICATE**

OK - T. SMITH

For corners in  
Oakland  
(County)

**COMMISSION**

Filing Requirement of Act 74, Mich. P.A. 1976

Located In: Orion  
Twp.

Corner Code #

1. Public Land Survey T 4N R 10E I-10  
T R  
T R  
T R
2. Property Controlling S T R  
in Section S T R
3. Miscellaneous S T R  
Property in Sec. S T R

7.00 MISCELLANEOUS RECORDING  
\$ 2.00 REMONUMENTATION  
27 JAN 95 11:01 A.M. RECEIPT# 76B  
PAID RECORDED - OAKLAND COUNTY  
LYNN D. ALLEN, CLERK/REGISTER OF DEEDS

Compliance with  
ACT 345, P.A. 1990

APPROVED ON: 12-29-94  
OAKLAND COUNTY REMONUMENTATION  
PEER GROUP COMMITTEE  
Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat
5. Private Claims

I, Huston K. Kennedy, in a field survey on December 20, 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

**A. Description of original monument and accessories and/or subsequent restoration:**

- 1817-GLO Wampler, D.S.; Set Post; 10" White Oak N70°E 15 Links; 16" Black Oak S22°E 16 Links  
1.) 1989-Bongiovanni, P.S. #24586; LCRC L.11191, Pg.418 - Fnd Iron Pipe  
2.) 1989-Bongiovanni, P.S. #24586; Survey L.11217, Pg.683 - Fnd Iron Pipe, used same wit as 1989 LCRC

	A	B	C	D	E	F	G	H	I	J	K	L
2	6		5		4		3		2		1	
3												
4	7		8		9		10		11		12	
5												
6	18		17		16		15		14		13	
7												
8	19		20		21		22		23		24	
9												
10	30		29		28		27		26		25	
11												
12	31		32		33		34		35		36	
13												

**B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:**

1994 Kennedy Surveying, Inc. - Kennedy, P.S. #17623 - Fnd 5/8" Iron Pipe 3" above ground 1.50' North to East-West fence line.

Witnesses from LCRC #1 were used to recover and verify the location of the found 5/8" Iron Pipe.

I accept the found 1/2" Iron Pipe as the best evidence of the original corner position.

**C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:**

I-10 I replaced the found 1/2" Iron Pipe with a 1/2" Iron Rod encased in a 4" diameter concrete cylinder 36" long w/2" diameter brass cap stamped Oakland County Remonumentation, PS #17623.  
N48°W 5.88' Set PK & Remon. Washer South face 37" Cherry  
N30°E 11.71' Set PK & Remon. Washer South face 14" Cherry  
S27°E 13.90' Set PK & Remon. Washer NE face 11" Elm  
S04°W 39.53' Set PK & Remon. Washer West face 17" Elm

The selected location is accepted by me and is generally accepted by Professional Surveyors as the best available evidence of the position of the original corner.

Signed by

Date January 6, 1995

Surveyor's Michigan License No. 17623

