

Surveyor's Michigan License No

Um 19758 N 526

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 LIBER 19758 PAGE LIBER 19738 PHBE 326
\$7.00 MISC RECORDING
\$2.00 REMONUMENTATION
03/30/1999 01:03:22 P.M. RECEIPT# 12968
PAID RECORDED - DAKLAND COUNTY
G. WILLIAM CADDELL, CLERK/REGISTER OF DEEDS For corners in Corner Code # Located in: 0akland (County) T 5N R 8E 1. Public Land Survey Compliance with ACT 345, P.A. 1990 JATION 6-13-58 55 2. Property Controlling APPROVED ON: OAKLAND COUNTY REMONUMENTATION in Section PEER GROUP COMMITTEE MAR 2 1 2000 3. Miscellaneous Register of Deeds Stamp & File Numbe Property in Sec. SECTION _, Recorded Plat 4. Lot No. 5. Private Claims I Timothy J. Hart, in a field survey on 3-30, 1998 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: Post set in 1815 G.L.O. survey; 9" B. Oak S 30°E 132 1ks; 6" Pin oak S 21°W 124 1ks. A) LCRC, L 6002, P 512, Albright, 1972, fd 1" pipe (2) B) LCRC, L 6965, P 133, Pangus, 1977, fd 3/4" pipe (2) C) LCRC, L 10836, P 725, Brown, 1989, fd 5/8" pipe in E-W fence line (4) (n) indicates number of witnesses confirmed B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Recovered a 1" pipe at the intersection of an east-west fence line and a north-south tree line, approximately 3/8 of a mile east of M-15 and a 1/2 mile north of Oakwood Road. Witnesses Confirmed N 45°W 58' Centerline 28" Maple (A) PROFESSION/ 36.55' Nail/tag NE 10" Ash (C) N 45°W 16.70' Nail/tag W 10" Ash (A, B&C) LAND LAND N 05°W No. 33136 22.35' Nail/tag W 8" Ash (B&C) N 35°E 14.58' Nail/tag S 10" Ash (C) s 80°W (L) indicates LCRC witness confirmed.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner. Replaced 1" pipe with concrete monument and O.C. Remon. brass cap. 16.65' PK/remon tag W 10" Ash 13.90' PK/remon tag S 10" Ash State Plane Coordinates N 05°W N 497616.5974 East 31.55' PK/remon tag W 12" Ash s 10°E E 13368368.6795 14.35' PK/remon tag S 10" Ash The selected location is accepted by the Contractor and is generally accepted by professional surveyors as the best available evidence of the position of the original corner. This corner was also accepted by the Oakland County Peer Group as established under Act 345 of P.A. 1990. Date Signed by 3136