

LIBER 15550 of 274

LAND CORNER RECORDATION CERTIFICATE \$ 7.00 MISCELLANEOUS RECORDING
Filing Requirement of Act 74, Mich. P.A. 1970 \$ 2.00 REMONUMENTATION

For corners in

Oakland (County)	Located in:	Addison Township	Corner Code #
1. Public Land Survey	T <u>5N</u>	R <u>11E</u>	<u>G-8</u>
	T _____	R _____	_____
	T _____	R _____	_____
	T _____	R _____	_____
2. Property Controlling in Section	S _____	T _____	R _____
	S _____	T _____	R _____
3. Miscellaneous Property in Sec.	S _____	T _____	R _____
	S _____	T _____	R _____

27 JUL 95 3:34 P.M. RECEIPT# 1408
PAID RECORDED - OAKLAND COUNTY
LYNN D. ALLEN, CLERK/REGISTER OF DEEDS

Compliance with
ACT 345, P.A. 1990

APPROVED ON: 6-26-95 Tomis
OAKLAND COUNTY REMONUMENTATION
PEER GROUP COMMITTEE

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Randy Kolehhouse, in a field survey on May 8 19 95,
do hereby certify that under requirements of P.A. 74 Michigan P.A. of 1970, the corner points
mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required
in the current manual of survey instructions of the United States Department of the interior, Bureau of
Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3,
4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a
Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered,
found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

G-8	1817	Wampler	G.L.O.	Set Post
	1914	Slater	County Surveyor's Records	
	1923	Slater	County Surveyor's Records	
	1986	Heil	Unrecorded Survey	Found Concrete Monument
	1989	Rossow	Unrecorded Survey	Set Iron
	1991	Kennedy	L.C.R.C. L. 12773 P. 521	Found 1/2" Iron Rod
	1992	Ward	L.C.R.C. L. 12560 P. 594	Found Monument

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

G-8 Found 4" concrete monument in cedar swamp on West side of Lakeville Lake, approximately 150' ± from shore. Also found
5/8" iron N 20° E 13.33'. Concrete monument appears to be old as it is moss covered. This monument has been held for
corner by all surveys shown above except the survey prepared by Rossow in 1989 in which he set an iron 13' M/L from the
concrete monument.

Heil Unrecorded Survey 1986

S 15° E 17.86' 10" Cedar

S 20° W 16.91' 14" Pine

N 10° E 39.89' 10" Pine

Kennedy L.C.R.C. L. 12773 P. 521 1991

S 15° E 17.86' N/W W Face 10" Cedar

S 20° W 16.91' N/W E Face 14" Pine

N 10° E 39.89' N/W NW Face 10" Pine

N 10° W 27.19' N/W E Face 10" Cedar

Ward L.C.R.C. L. 12560 P. 594 1992

S 25° E 10.99' PK & Disc. #22445 SW Face 5" Evergreen

S 35° W 12.93' PK & Disc. #22445 SE Face Twin 6" Cedar

N 27° W 27.34' PK & Disc. #22445 E Face 8" Cedar

N 50° E 9.18' PK & Disc. #22445 SE Face 3" Cedar

Heil Measures North 2781.7' to G-7 and West 2763.2' to I-8

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-8 Placed a brass cap stamped "Oakland County Remonumentation P.S. #25854" on an existing monument.

PK Nail & Tag Stamped "Oakland Co. Remonumentation P.S. #25854" in NW Face 12" Pine N 28° E 39.90'

PK Nail & Tag Stamped "Oakland Co. Remonumentation P.S. #25854" in W Face 6" Pine S 28° E 11.00'

PK Nail & Tag Stamped "Oakland Co. Remonumentation P.S. #25854" in E Face Twin 6" Cedar S 40° W 12.95'

PK Nail & Tag Stamped "Oakland Co. Remonumentation P.S. #25854" in E Face 8" Cedar N 24° W 27.38'

The selected location is accepted by the Contractor and is generally accepted by professional
surveyors as the best available evidence of the position of the original corner.

Signed by Randy J Kolehhouse

Date 7/14/95

EARTH TECH

Surveyor's Michigan License No. 25854

