LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

Oceana	Located In	Corner Code #	
(County)			
1. Public Land Survey	T 14N R 16W	E11	
Property Controlling in Section Miscellaneous Property in Section	S T R S S T R R S S T R R S T R R S T R R S T R R S T R R S T R R S T R R R S T R R R S T R R S T R R R S T R R R S T R R R R		Decision of Decision Officers 9, 531e November
	3		Register of Deeds Stamp & File Number
4. Lot No:	Recorded Plat:		ABCDEFGHIJKLM
5. Private Claims:			1 2 6 5 4 3 2 1
requirements of PA 74, Mic and 2 above were in confo- the current manual of sur Interior, Bureau of Land Ma corner points mentioned in of the Michigan Board of	Tield survey on March 8, 2016 do here chigan PA of 1970, the corner points normance with regulations and rules there was instructions of the United States an agement or by a decree of a Court of lines 3, 4 and 5 above were in conform f Land Surveyors or by a Decree of monumented, recovered, found as exp	eby state that under mentioned in lines 1 refore as required in Department of the Law and/or that the mance with the rules 7 of a Court of Law; and seed below;	3 4 7 8 9 10 11 12 15 6 18 17 15 14 13 7 8 19 20 21 22 23 24 9

A. Description of original monument and accessories and/or subsequent restoration:

NOTE: Not more than 2 corners, all in the same town and range, may

E11 - 1838 - GLO - J. H. Mullett - Set Post

1) Beech 10" N60°E 35 L.

be recorded on this certificate.

- 2) Beech 24" S61°W 10 L.
- 1891 CSR 'A', p. 289 H. A. Grant

Stake with lime around it. Set several years ago by Edson - 1957 - OCRC - 1° iron rod

- 3) Fence post w/ MSHD Pt. Due S. 30.38'.
- 4) Fence post w/ MSHD Pt. S60°W 58.05'
- 5) Fence Cor. of Cemetery N45°W 47.39'

- 1963 MDOT Hwy. Plan #64022 A. -42.04' lf. of station 376+86.29. Fd. 1" iron;

- 5) N45°W Cemetery Cor. Post 47.66'; 4) S65°W Fe. Post 58.24'; 3) Due S. Fe. Post 30.45.
- 1985 MDNR Field notes Fd. ½" rerod in Mon. Box 2003 Record Survey SV 781 J. R. Hepworth (PS #26457). Fd. Iron in Mon. Box 42.04' N. of Center Hwy.
- B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
- E11 Corner common to Sections 28, 29, 32 & 33 Found 1/2" rebar in Monument Box. Witnesses #1 through 5 are gone. Phy. centerline of M-20 is 43'± South. In centerline of gravel road to North. Accepted 1/2" rebar in Mon. Box as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E11 - 1/2" rebar in monument box.

S29°E 139.04' to set Spike and Tag in NE side 20" W. Pine N62°W 87.60' to chiseled 'X' in SE Comer Concrete wall in cemetery N13°E 139.25' to top of 2 ½" - 'L' iron fence post in concrete N12°W 192.71' to set Mag. Spike and Tag in E. side 45" Maple



Signed by:

Surveyor's Michigan License No.: 39088

Date: