

SURVEY & REMONUMENTATION

OCT 27 1993

COMMISSION

OCEANA COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN COUNTY OF OCEANA RECEIVED FOR RECORD 100497 '93 OCT -7 P2:44

For corners in

OCEANA (County)

Located In:

Corner Code #

- 1. Public Land Survey T 14N R 18W I-11
- 2. Property Controlling in Section S T R
- 3. Miscellaneous Property in Sec. S T R
- 4. Lot No. , Recorded Plat
- 5. Private Claims

Jeff E. Martin REGISTER OF DEEDS

Register of Deeds Stamp & File Number

J. Randolph Hepworth in a field survey on September 30, 1993

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2								
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

A. Description of original monument and accessories and/or subsequent restoration:

I-11 CORNER COMMON TO SECTIONS 26, 27, 34, AND 35 BENONA TWP; T14N, R18W
GLO 12" HEMLOCK FOR POST No Witnesses Recited
GLO CALL: STREAM CROSSING SE-NW EAST 660' FROM CORNER I-11
BOOK A-274 GRANT, 1891 SET STAKE 12" CEDAR N60°E 11.9' 6" CEDAR N37°W 15.2
BOOK A-276 GRANT, 1891 SAME

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner

REESTABLISHED CORNER BY GRANT, 1891 DISTANCE FROM N 1/4 CORNER OF SECTION 35 AND PROJECTING LINE THRU FENCE CORNER INTERSECTION AT APPROX. 1/16 CORNER BETWEEN N 1/4 CORNER AND NW CORNER OF SECTION 35. THIS POSITION FITS GRANT, 1891 DISTANCE FROM W 1/4 CORNER OF SECTION 35.
A DRY & SHALLOW STREAM BED -COURSE SE-NW IS EAST 660' +/- 5' FROM CORNER I-11.
THIS CORNER IS ACCEPTED AS A CAREFUL AND FAITHFUL REESTABLISHMENT OF THE POSITION OF THE ORIGINAL CORNER.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

I-11 CORNER COMMON TO SECTIONS 26, 27, 34, AND 35
SET "COUNTY SURVEYOR" HARRISON 4"x20" CAST IRON MONUMENT AT REESTABLISHED POSITION

60d SPK S FACE	6" CEDAR	S80°E	12.68' TAPED
60d SPK NE FACE	18" BASSWOOD	S45°E	41.35' TAPED
60d SPK W FACE	10" HEMLOCK	SOUTH	26.54' TAPED
60d SPK N FACE	6" CEDAR	S15°W	5.23' TAPED
60d SPK SW FACE	8" CEDAR	N60°W	6.20' TAPED
60d SPK W FACE	8" TW MAPLE	N10°E	22.35' TAPED



Signed by [Signature] Date October 6, 1993
Surveyor's Michigan License No. 26457