SURVEY &

JAN 182001

RECTION

For corners in

Signed by

Surveyor's Michigan License No.

26457

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN COUNTY OF OCEANA RECEIVED FOR RECORD

21 DEC 2000 3:19:44 PM

Oceana (County)	Located In:	Corner Code #	:		EPH'E. MERTEN DISTER OF DEEDS	
1. Public Land Survey	T16NR15W TR TR	C-8			105	L020
2. Property Controlling in Section S. Miscellaneous Property in Sec.	6 T R 6 T R	`		Register of De	eeds Stamp & Fil	le Numbel
4. Lot No, Recorded	Plat			A B C D E	FGHI	J K L
5. Private Claims				2 6 5		
requirements of P.A. 74, Michigan P.A. conformance with regulations and rules United States Department of the Interior that the corner points mentioned in lim Board of Land Surveyors or by a D recovered, found as expressed below:	A. of 1970, the corner point s therefore as required in the or, Bureau of Land Managen es 3, 4 and 5 above were in	s mentioned in fines 1 and current manual of survey in nent or by a decree of a Co conformance with the rule	I 2 above were in instructions of the urt of Law and /or s of the Michigan	3 4 - 7 - 8 - 5 6 - 19 - 17 - 7 8 - 19 - 20 - 20	9 10 15 15 21 22 22	1112
NOTE: Not more than 2 comers, all in the same town and range, may be recorded on this certificate.			9 10 30 29	28 27	26 -25	
				11 32 32 32	33 34	35 36
A. Description of original monum	ent and accessories and	l/or subsequent restora	tion:			
C-8 1/4 CORNER COMMON TO S	ECTIONS 19 & 20 T1	6N, R15W COLF	AX TOWNSHIP			
GLO John Hodgson 1838 SET POS	T 6" Beech N47°W 4	1 lks 10" Beech S46°	E 12lks			
LCRC # 100353, K. Ross #17634, 6. halfway and on line between the SE 5"X5"X36" reinforced concrete post is stamped as follows: T16N, R15W, 1) 8" R. Pine N52"W 39.98"	corner and the NE corner set 1.0 feet below the road , 1/4, S19, S20, 1986, LLS	of Section 19. On June I surface. A 3" diameter I	16, 1986, I set (at orass disk is cast t	the exact location of ti	s monument. The	corner) a
Recorded Survey, Jkt #382, K. Ross	#17634, 6/26/86; See LC	RC#100353			•	
B. Description of corner evide	ence found and/or me	thod applied in resto	ring or reestab	lishing corner.		
I found a 5"x5" sq., conc. Monument All witnesses are standing and meas and on the south side of the monum east.	sure OK As this monume	nt was only slightly detec	table with the met	al locator. I set a 1/2"	(24" fron on the no	rtn side
I accept this monument as the best a corner should be at another location	available evidence of the p	osition of the original cor a substantial marker in u	ner. No evidence ndisturbed conditi	is known to me that v on, I left it as found.	vould lead me to be	elieve the
C. Description of monument	for corner and accesso	ories established to pe	erpetuate locati	ng the position of	the corner:	
5"x5" sq., conc. Monument with bras 1) Ex. 60d spk w/ blaze 2) Set 60d spk above ex. 60d spk w 3) Ex. 60d spk w/ blaze Set 60d spk Set 60d spk	NE Face	"T16N, R15W, 1/4, S19 9" R Pine 30" Maple 18" tw W Oak Power Pole Power Pole	9, S20, 1986, LLS 308°az 50°az 247°az 22°az 169°az	17634" 39.99' 50.56' 39.85' 176.01' 235.95'	EDM EDM EDM EDM EDM	
		L. Sur Surfa		Occupa County E. Foor Group Review Date:	9-00 CH orth	un .

Date