FEB 2 5 1994 Oceana County Remonumentation Peer Group Reviewed & Approved COCEANA COUNTY REMONUMENTATION& //-/8-93 Date. IRN LAND CORNER RECORDATION CERTIFICATE 100519 J. Randolph Hepworth Filing Requirement of Act 74, Mich. P.A. 1970 Steanhergunty Surveyor **OCEANA** Located In: Corner Code ## STATE OF MICHIGAN COUNTY OF DOCUMENTA RĚČĚÍVĚD FOR ALLURD T16N R 17W **Public Land Survey** G-8__ R __ __ R DEC 14 A10:23 R **Property Controlling** S _ R in Section S R mertino Miscellaneous S __ R Register & Deeds Stamp & File Number Property in Sec. T R $oldsymbol{\bot}$, Recorded Plat $oldsymbol{\bot}$ Private Claims _ J. Randolph Hepworth in a field survey on November 29, 1993 hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned lines 1 and 2 above were in conformance with regulations and rules therefore as required in the irrent manual of survey instructions of the United States Department of the Interior, Bureau of Land anagement or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 hove were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a ourt of Law; established, re-established, monumented, re-monumented, recovered, found as pressed below: 10 OTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. Description of original monument and accessories and/or subsequent restoration: A. G-8 1/4 CORNER COMMON TO SECS 21 & 22, T16N, R17W WEARE TOWNSHIP GLO SET POST 24" HEMI OCK \$10°W 12" B ASH N86°E 11.9" BOOK A-444 FF WETMORE, 18970 BOOK A-466 EM HYDE, 1911 1/2"X36" IRON BY J. BEAN, 1882 FOUND 1/2" IRON OCRC WITNESS - SAME AS BLASS- CONSUMERS POWER CONSUMERS POWER CO., G BLASS, RLS 1968 FOUND 1/2" IRC S END STONE HEADWALL S78°E 16.87 NAIL/O E EDGE STONE HEADWALL AT ANGLE IN WALL N87°E 11.00 FOUND 1/2" IRON NAIL/CAP P POLE S13°E 153.14 LCRC #100249 G BONNEY, 11-29-79 FOUND 1/2" RE-ROD S END HEADWALL S78°E 16.87 DEFL. HEADWALL N87°E 11.0 P POLE S82°E 33.75 B.Description of corner evidence found and/or method applied in restoring or reestablishing corner I found a 5/8" from per LCRC #190249 This monument is not a 1/2" fron described by Bonney or Blass. Further search of this area yielded no evidence of a conflicting position of the corner. This represents the best available evidence for the position of the corner. This 5/8" IRON IS ACCEPTED AS A CAREFUL AND FAITHFUL PERPETUATION OF THE POSITION OF THE ORIGINAL CORNER. REMAINS OF HEADWALL VISIBLE OR FOUND. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner. G-8 1/4 CORNER COMMON TO SECS 21 & 22, T16N, R17W WEARE TOWNSHIP SET "COUNTY SURVEYOR" HARRISON 4"X20" CAST IRON MONUMENT IN PLACE OF FOUND 5/8" IRON PK NAIL W FACE POWER POLE N07°F 248,52 **EDM** CENTER GAS LINE MARKER N05°W 262,94 **EDM** PK NAIL E FACE POWER POLE \$10°E 385.17 FOM 60d SPK S FACE POWER POLE NAIL/BLASS CAP W FACE P POLE FOWER POLE 32,96 TAPE S81°E 32.7 TAPE

ined by rveyor's Michigan License No. _ 26457

GAS LINE MARKER

CENTER

of MICHICA J. RANDOLPH HEPWORTH LANDate **SURVEYOR**

-AQ

MINISTERED LAND

\$77°F

N15°E

becember 1, 1993

76.90

139.1

REVISED MAY 14, 1975 REVISED JAN., 1983

TAPE

EDM