

Ogemaw County Remonumentation  
LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

FEB 24 2000

For corners in

Ogemaw  
(County)

Located in:

Corner Code #

SECTION

1. Public Land Survey

T22N R02E  
T22N R 03E  
T R  
T R  
S T R  
S T R  
S T R  
S T R

M-5  
A-5

2. Property Controlling  
In Section

3. Miscellaneous  
Property In Sec.



3006792

Page: 1 of 1  
12/27/1999 09:09A  
L-4 P-1

Wanda Muzik, Ogemaw Co. Register SURC 9.00

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

I, Timothy L Lapham, in a field survey on December, 19 99 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mention in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate

|    | A  | B | C  | D | E  | F | G  | H | I  | J | K  | L | M |
|----|----|---|----|---|----|---|----|---|----|---|----|---|---|
| 1  |    |   |    |   |    |   |    |   |    |   |    |   |   |
| 2  | 6  |   | 5  |   | 4  |   | 3  |   | 2  |   | 1  |   |   |
| 3  |    |   |    |   |    |   |    |   |    |   |    |   |   |
| 4  | 7  |   | 6  |   | 9  |   | 10 |   | 11 |   | 12 |   |   |
| 5  |    |   |    |   |    |   |    |   |    |   |    |   |   |
| 6  | 18 |   | 17 |   | 16 |   | 15 |   | 14 |   | 13 |   |   |
| 7  |    |   |    |   |    |   |    |   |    |   |    |   |   |
| 8  | 19 |   | 20 |   | 21 |   | 22 |   | 23 |   | 24 |   |   |
| 9  |    |   |    |   |    |   |    |   |    |   |    |   |   |
| 10 | 30 |   | 29 |   | 28 |   | 27 |   | 26 |   | 25 |   |   |
| 11 |    |   |    |   |    |   |    |   |    |   |    |   |   |
| 12 | 31 |   | 32 |   | 33 |   | 34 |   | 35 |   | 36 |   |   |
| 13 |    |   |    |   |    |   |    |   |    |   |    |   |   |

A. Description of original monument and accessories and/or subsequent restoration:

GLO by L. Clason, 1838, Post  
N61W 6 ft 12" Hd Maple  
S68W 41 ft 12" Hd Maple

LCRC by R. Higgins, 1982, 1/2" bar  
East 51.35 Hwy Marker  
S45W 67.68 Spike in Power Pole  
S20W 94.35 No Parking Sign  
S20E 93.0 No Parking Sign

Survey by N. Caldwell, 1975, No material

Consumers Power Survey, 1965+, Found Pk nail  
West 50.9 Power Pole  
East 51.35 Hwy Markers

Approved by Peer Review

12-1649  
DATE INITIALS

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:  
No GLO evidence found. Found 1/2" capped iron in monument box. Found 1 - 1965 witness and 4 - 1982 witnesses. Distances to M/A-3 and M/A-7 match 1965 survey. Accepted found iron as best available evidence of correct corner position.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 5/8" rerod w/aluminum remon cap  
East 51.20 R/W Marker  
S54E 58.88 10" Maple  
S32E 68.39 8" Maple  
S52W 67.65 Utility Pole  
East 1.4 Centerline M-33

Signed by

Surveyor's Michigan License No. 27595

Date

12/23/1999