

Ogemaw County Remonumentation
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

FEB 24 2000

SECTION

3006792

Page: 1 of 1
12/27/1999 09:09A
L-4 P-1



Wanda Muzik, Ogemaw Co. Register SURC 9.00

Register of Deeds Stamp & File Number

or corners in

Ogemaw
(County)

Located in:

Corner Code #

Public Land Survey

T22N R02E

M-5

T22N R 03E

A-5

T R

T R

T R

T R

T R

T R

Property Controlling
in Section

S

S

S

S

Miscellaneous
Property in Sec.

Lot No. , Recorded Plat
Private Claims

Timothy L Lapham, in a field survey on December, 19 99, do hereby state
at under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mention
lines 1 and 2 above were in conformance with regulations and rules therefore as required in
a current manual of survey instructions of the United States Department of the Interior,
Bureau of Land Management or by a decree of a Court of Law and/or that the corner points
mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board
of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented,
covered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate

Description of original monument and accessories and/or subsequent restoration:

GLO by L. Clason, 1838, Post
N81W 61k 12" Hd Maple
S88W 41 k 12" Hd Maple

LCRC by R. Higgins, 1982, 1/2" bar
East 51.35 Hwy Marker
S45W 67.68 Spike in Power Pole
S20W 94.35 No Parking Sign
S20E 93.0 No Parking Sign

Survey by N. Caldwell, 1975, No material

Consumers Power Survey, 1965+-, Found Pk nail
West 50.9 Power Pole
East 51.35 Hwy Markers

Approved by Peer Review

12-16-99
DATE INITIALS

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No GLO evidence found. Found 1/2" capped iron in monument box. Found 1 - 1965 witness and 4 - 1982 witnesses. Distances to WA-3 and WA-7 match
1965 survey. Accepted found iron as best available evidence of correct corner position.

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 5/8" rerod w/aluminum remon cap
East 51.20 R/W Marker
S54E 58.68 10" Maple
S32E 66.39 6" Maple
S52W 57.65 Utility Pole
East 1.4 Centerline M-33

igned by
urveyor's Michigan License No. 27595

Date 12/23/1999