

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:
Ogemaw
(County)

Located In

Corner Code #

1. Public Land Survey	T	23N	R	1E	B-3
	T	23N	R	1E	C-3
2. Property Controlling in Section	S	T	R		
	S	T	R		
3. Miscellaneous Property in Section	S	T	R		
	S	T	R		

4. Lot No: Recorded Plat:

5. Private Claims:

I, Carl T. Kiiskila, in a field survey on January 12, 2006 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

A	B	C	D	E	F	G	H	I	J	K	L	M
1												
2	6	5	4	3	2	1						
3	7	8	9	10	11	12						
4												
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

A. Description of original monument and accessories and/or subsequent restoration:

B-3 G.L.O. James Mullet 1846 set quarter section post
Wit: Spruce 3" N66°E 25 links
Spruce 4" S44°W 5 links

C-3 G.L.O. James Mullet 1846 set post corner to sections 5,6,7, and 8

Wit: Spruce Pine 5" S55°W 4 links
Spruce Pine 5" N19°E 13 links

Marcus Schaaf RLS #3104 index indicates he used this corner circa 1940 to set the center of section 6. Type of monument and witnesses not given.

September 1977 Robert Higgins RLS #21570 notes indicate he found a bent 2" pipe for corner, no witnesses given.

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

B-3 Re-established the 1/4 corner common to sections 6 and 7, by extending a line from the North 1/4 corner of section 6 thru the found center of section 6 and intersecting it with a line between the Southeast and Southwest corner of section 6.

C-3 Found a cabin spike fitting R. Higgins survey in section 5.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

B-3 Set 1" X 48" pipe with standard DNR cap.
Wit: 20" Cedar S37°E 67.83'
5" Spruce S22°W 24.03'
8" Maple N45°E 16.73'
4" Spruce S76°W 37.98'
Blue Carsonite Post North 1'±

C-3 Set 1" X 32" Pipe with standard DNR cap.
Wit: 5" J. Pine N19°E 3.99'
4" J. Pine S24°W 9.12'
4" J. Pine N61°W 10.03'
4" J. Pine N80°E 11.24'
Centerline of N-S Rd West 33'±

Signed by:

Carl T. Kiiskila

Date:

1-31-06

Surveyor's Michigan License No.:

33981

