

# SURVEY & REMONUMENTATION

MAR 02 2001

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

SECTION

For corners in

ONTONAGON  
(County)

Located In:

Corner Code #

1. Public Land Survey

T48N R40W E - 2

2. Property Controlling  
in Section

S T R

3. Miscellaneous  
Property in Sec.

S T R

JUDITH D. ROEHM

1P

Ontonagon County

Page 1 of 1

LC 5/346

JEM Date 11/01/2000

Time 12:12:48

RECORDING FEE:

9.00

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

$\frac{1}{4}$  Corner common to Sections 4 & 5, T48N R40W.

I, Earl W. Applekamp, in a field survey on Oct. 18, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established by Wells Burt, U.S. Deputy Surveyor, June 2, 1851. Set Wood Post.

ORIGINAL BEARING TREES:

10" Hemlock N45°W 14 Links (9.24 Feet)  
6" Sugar S32°E 15 Links (9.90 Feet)

DEED GROUP APPROVED  
Earl W. Applekamp  
COUNTY DEEDS & RECORDS  
10-25-00

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No original evidence was found. Any evidence would have been destroyed by a county road which turns to the West near the corner. An unimproved road continues North from the  $\frac{1}{4}$  Corner for  $\frac{1}{2}$  mile. Corner was re-established by single proportionate measure between opposite corners North and South and on the center-line of the road projected North and South.

Research on file with the Ontonagon County Remonumentation Program Representative.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

At the corner position I set a 2 $\frac{1}{2}$ "x30" split base aluminum pipe with a 3" cap stamped to read: County Remonumentation, T48N R40W,  $\frac{1}{4}$ , S4, S5, 2000, P.S. 17610. I established three bearing trees and a reference object.

Nail in 5" Maple S69°W 76.85' - Nail in 8" Black Ash S78°E 47.05'  
Nail in 5" Maple N25°W 87.18' - 6' Steel Sign Post West 0.65'



Signed by Earl W. Applekamp  
Surveyor's Michigan License No. 17610

Date October 23, 2000