

**MAR 02 2001**

**LAND CORNER RECORDATION CERTIFICATE  
Filling Requirement of Act 74, Mich. P.A. 1970**

**SECTION**

For corners in

Ontonagon County

Located in:

Corner Code #

**JUDITH D. ROEHM**

**1P**

Ontonagon County

Page 1 of 1

**LC 5/357**

**JEM Date 12/08/2000**

**Time 11:43:18**

**RECORDING FEE:**

**9.00**

1. Public Land Survey

T48N R41W

A-12

T48N R42W

M-12

T R

T R

T R

T R

T R

2. Property Controlling  
in Section

S

T R

S

T R

3. Miscellaneous  
Property in Sec.

S

T R

4. Lot No.

, Recorded Plat

5. Private Claims

**Register of Deeds Stamp & File Number**

I, Joseph C. Domitrovich, in a field survey on November 2, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE:** Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5			4		3		2		1	
3													
4	7		8			9		10		11		12	
5													
6	18		17			16		15		14		13	
7													
8	19		20			21		22		23		24	
9													
10	30		29			28		27		26		25	
11													
12	31		32			33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

(A - 12/M - 12) ¼ Corner Common to Section 31, T48N, R41W, and Section 36, T48N, R42W.

1847 - William A. Burt set a Cedar post with ties:

14" Cedar	S 78°E	14 links
10" Maple	N 14°W	24 links

I found no record of Subsequent restoration.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I found no evidence of the original corner or accessories. At the corner position I found a 1" O.D. pipe with grown over blazes facing the pipe. The pipe also falls on a North - South blazed blue painted line. The pipe works very well with GLO distances to Section Corners North & South. I accepted the 1" iron pipe as the section corner and Monumented it as such.

Research on file with County Remonumentation Representative.

**DEED GROUP APPROVAL**


*Earl W. Applebaum*  
**COUNTY REMONUMENTATION**  
**11-29-00**

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner is a 5/8" x 48" iron pin with a 3" diameter aluminum cap placed on it, driven inside of a 1" iron pipe. Cap is stamped to read: COUNTY REMONUMENTATION; T48N, R42W, R41W; ¼; S. 36, S. 31; 2000; P.S. 37273. Ties:

9" Cedar	N 10°E	17.16'
8" Cedar	S 70°E	17.51'
Steel Sign Rail	South	0.67' (to face)
8" Cedar	N 33°W	4.63'
SW Cor. Sec. 31	S 00°01'20"W	2628.44'
NW Cor. Sec. 31	N 00°04'13"W	2633.71'

**NOTE:** Bearings to witness objects are magnetic. Distances are to a nail in side of the witness object unless noted. Bearings shown between corners are on assumed basis, for reference only.



Signed by

*Joseph C. Domitrovich*

Date

*11/28/00*

Surveyor's Michigan License No. 37273