LC 5/282

Page 1 of 1 Time 15:11:32 JEM Date 05/30/2000 9.00

## LAND CORNER RECORDATION CERTIFICATE

| Filing Requirement of Act 74, Wilch. F.A.  | 10.0  |
|--|---|
| For corners in  COTTONAGON Located In: Corner Code #   | SURVEY & REMONUMENTATION  |
| (County)  1. Public Land Survey  T48N R41W  T R  | MAR 0 2 2001  |
| T_R  | SECTION   |
| 2. Property Controlling  |   |
| 3. Miscellaneous S TR  | Register of Deeds Stamp & File Number                               |
| 5. Private Claims  Section Corner common to Sections 2, 3, 10 & 11, T48N R41W.  1. Earl W. Applekamp, in a field survey on May 22, deep do hereby state that unconformance with regulations and rules therefore as required in the current manual of survey instructions of conformance with regulations and rules therefore as required in the current manual of survey instructions of United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law, and 5 above were in conformance with the rules of the Michig Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monument recovered, found as expressed below.  NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.  | ter 4 7 8 9 11 11 11 11 11 11 11 11 11 11 11 11 1                   |
| <ul> <li>A. Description of original monument and accessories and/or subsequent restoration:</li> </ul>   |   |
| Original Corner established by Wells Burt, U.S. Deputy Surv<br>June 17, 1851. Set Wood Post.   | reyor,  |
| ORIGINAL BEARING TREES:  | PEER GROUP APPROXIM   |
| 30" W. Pine North 18 Links (11.88 feet<br>40" W. Pine S45°W 26 Links (17.16 feet   | COLLANA BUNGALTANA 2-54-0   |
| B. Description of corner evidence found and/or method applied in restoring or reestablishing No original evidence was found. There was a blue paint line paint line running South and two trees with a great deal of near the calculated search area. These were used for logging feet of where I ultimately set the corner. Corner was research areasurement between the SW Corner of Section 4 West, the Source of Section 100 or 10 | paint on them, about 50 feet aparting the area and are within a few |

NE Corner of Section 3 North and the SE Corner of Section 10 So

Research on file with the Ontonagon County Remonumentation Program Representative.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: At the Corner position I set a  $2\frac{1}{2}$ "X30" split base aluminum pipe with a 3" cap stamped to read: County Remonumentation, T48N R41W, S2, S3, S10, S11, 2000, P.S. 17610. I established three bearing trees and a

reference object.

S10°₩ Nail in 4" Aspen Nail in 7" Maple N14°W

40.58' - Nail in 6" Maple \$75°E 31.31' - 6' Steel Sign Post, West

18.941 0.69

EARL W.

APPLEKAMP
PROFESSIONAL
NO,
17610
OFESSIONAL
ARRIVATION
MARRIES
ARREST

| Signed by Sail W applekaup     |       |
|--------------------------------|-------|
|                                | 17610 |
| Surveyor's Michigan License No |       |

May 23, 2000 Date\_

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1871

REVISED MAY 14,1975 REVISED JAN., 1983 REVISED OCT., 1985