JUDITH D. ROEHM
Ontonason County
Page 1 of 1
JEM Date 10/03/2000 Time
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74 Mach. B. A. 4070 LC 5/340 Time 10:36:07 9.00

Filing Requirement of Act 74, Mich. P.A.	1970
For corners in  CNTONACON Located in: Corner Code#	SURVEY & REMONUMENTATION
(County)	
1. Public Land Survey  T48 R41	MAR 02 2001 SECTION
2. Property Controlling       S       T       R         In Section       S       T       R         3. Miscellaneous       S       T       R         Property in Sec.       S       T       R	Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat 5. Private Claims	ABCDEFGHIJKL
Section Corner common to Sections 1 & 2, T48N R41W & Sections 35 & 36, T49N R41W.	2 5 5 1 3 2 1 - 3
I. Earl W. Applekamp. In a field survey on Sept. 21, 10: 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /o that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigal Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented recovered, found as expressed below:	n 5
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.	9 10 30 29 28 27 26 25 11 12 31 32 33 34 35 36
A. Description of original monument and accessories and/or subsequent restoration:	
Original Corner established by William A. Burt, U.S. Deputy Surveyor, summer of 1847. Set Cedar Post.	
ORIGINAL BEARING TREES:	DEER GROUP AVENUALLY
14" Cedar N25°E 21 Links (13.86 Feet) 14" Hemlock N44°W 15 Links (9.90 Feet)	Collect Explication
B. Description of corner evidence found and/or method applied in restoring or reestablishing of	
No original evidence was found. Calculated Corner position road running North & South with some gravel, but now is gracalculated position an old fence runs East and West with firm this position. I re-established the corner at the intline of the old road and the fence lines East & West as being position for the corner.	ss covered. From the elds being farmed NE & SW ersection os the center- ng the only logical
Research on file with the Ontonagon County Remonumentation	Program Representative.
C. Description of monument for corner and accessories established to perpetuate locating the	position of the corner:
At the corner position I set a $2\frac{1}{2}$ "X30" split base aluminum I 3" cap flush with the top of the old road. Cap is stamped to County Remonumentation, T49N, T48N, R41W, S1, S2, S35, S36, P.S. 17610. I established 3 bearing trees and a reference of	to read: 2000, pbject.  professional surveyor of No. 17610
Nail in 8" Aspen N74°W 87.11' - Nail in 5" Aspen S Nail in 6" Aspen N16°W 108.86' - 6' Steel Sign Post	S10°E 135.75' Topession Resident
Signed by Lack W Caplificance Date Surveyor's Michigan License No. 17610	September 25, 2000