SURVEY & REMONUMENTATION

MAR 02 2001

LAND CORNER RECORDATION C Filing Requirement of Act 74, Mich	ERTIFICATE DA 1070
For corners in	SECTION
ONTONAGON Located In: " Corner Code #	
(County)	JUDITH D. ROEHM
1. Public Land Survey T48N R 41W K-2	Ontonagon County
TR TR	IEM Date 11/01/2000 Time 12:12:40
T	RECORDING FEE: 9.06 Register of Deeds Stamp & File Number
	Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat	A B C D E F G H I J K L
1/4 Corner common to Sections 1 & 2, T48N R41W.	2 6 5 4 3 2 4 1
I, <u>Earl W. Applekamp</u> , in a field survey on <u>Oct. 05</u> , %S. do hereby state the requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above conformance with regulations and rules therefore as required in the current manual of survey instruction. United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Lathat the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, mont recovered, found as expressed below:	9 were in so of the 5
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.	9 29 28 27 26 25 11 12 32 33 34 35 36
Description of original monument and accessories and/or subsequent restoration:	13
Original Corner established by Wells Burt, U.S. Deputy S June 19, 1851. Set Wood Post.	urveyor,
ORIGINAL BEARING TREES:	
14" Cedar N35°W 2 Links (1.32 feet) 16" Cedar S10°W 11 Links (7.26 feet)	
B. Description of corner evidence found and/or method applied in restoring or reestablis	hing corner:
No original evidence was found. All original evidence a road and farming. Corner was re-established by single measure between opposite corners, North & South.	was destroyed by proportionate
Research on file with the Ontonagon County Remonumentation Representative.	on Program
	PEER BROW AFRICA
	Lack W aplekans
C. Description of monument for corner and accessories established to perpetuate locating	COLERY MANAGERIA
At the corner position I set a $2\frac{1}{2}$ "X30" aluminum pipe with stamped to read: County Remonumentation, T48N, R41W, S1 2000, P.S. 17610. I established two bearing trees and to objects.	h a 3" cap
Nail in 5" Aspen S43°W 111.89' - Nail in P. Po Nail in 10" Spruce N87°E 50.75' - 6' Steel Sign Post	ole N27°E 37.22' Surveyor
I a fel Dal	
<i>,</i> , , , , , , , , , , , , , , , , , ,	October 7, 2000
Surveyor's Michigan License No. 17610	