

**LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970**

**MAR 02 2001**

For corners in

Ontonagon County

Located in:

Corner Code #

1. Public Land Survey

T48N R41W A-11  
T48N R42W M-11

**JUDITH D. ROEHM**

**1P**

**Ontonagon County**

**Page 1 of 1**

**LC 5/356**

**JEM Date 12/08/2000**

**Time 11:42:59**

**RECORDING FEE:**

**9.00**

2. Property Controlling  
in Section

S T R  
S T R

3. Miscellaneous  
Property in Sec.

S T R  
S T R

4. Lot No. , Recorded Plat

5. Private Claims

**Register of Deeds Stamp & File Number**

	A	B	C	D	E	F	G	H	I	J	K	L	N
1													
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

I, Joseph C. Domitrovich, in a field survey on November 3, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE:** Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

**A. Description of original monument and accessories and/or subsequent restoration:**

(A-11/M-11) Section Corner Common to Sections 30 & 31, T48N, R41W, and 25 & 36, T48N, R42W.

1847- William A. Burt set a Cedar post with ties:

16" Hemlock	N 22°E	28 links
16" Cedar	S 17°W	28 links

I found no Record of Subsequent restoration.

**B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:**

I found no evidence of the original corner or accessories. At the corner position I found a 1" O.D. pipe with a very rusty yellow Forest Service location poster facing it. The pipe works very well with GLO distances to the north and south. I accepted the 1" iron pipe as the section corner and Monumented it as such.

Research on file with County Remonumentation Representative.

**C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:**

Corner is a 5/8" x 48" iron pin with a 3" diameter aluminum cap driven inside of a 1" iron pipe. Cap is stamped to read: COUNTY REMONUMENTATION; T48N, R41W, R42W; S. 25, S. 36, S. 30, S. 31; 2000, P.S. 37273. Ties:

8" Dead Conifer	West	15'	(w/ Location Poster)
5" Hard Maple	N 03°E	17.69'	
9" Ash	N 55°E	12.35'	
4" Hard Maple	S 67°E	16.32'	
Steel Sign Rail	S 54°W	0.61'	(to face)
W 1/4 Cor. Sec. 31	S 00°04'13"E	2633.71'	
W 1/4 Cor. Sec. 30	N 00°00'51"E	2629.66'	



**NOTE:** Bearings to witness objects are magnetic. Distances are to a nail in side of the witness object unless noted. Bearings shown between corners are on assumed basis, for reference only.

Signed by Joseph C. Domitrovich

Date 11/28/00

Surveyor's Michigan License No. 37273