

MAR 02 2001

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

SECTION

For corners in

Ontonagon County

Located in:

Corner Code #

JUDITH D. ROEHM

1P

Ontonagon County

1. Public Land Survey

T48N R41W

A - 12

Page 1 of 1

LC 5/357

T48N R42W

M - 12

JEM Date 12/08/2000

Time 11:43:18

RECORDING FEE:

9.00

2. Property Controlling
in Section

S

T

R

3. Miscellaneous
Property in Sec.

S

T

R

S

T

R

4. Lot No. , Recorded Plat

5. Private Claims

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5			4		3		2		1	
3													
4	7		8			9		10		11		12	
5													
6	18		17			16		15		14		13	
7													
8	19		20			21		22		23		24	
9													
10	30		29			28		27		26		25	
11													
12	31		32			33		34		35		36	
13													

I, Joseph C. Domitrovich, in a field survey on November 2, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(A - 12/M - 12) 1/4 Corner Common to Section 31, T48N, R41W, and Section 36, T48N, R42W.

1847 - William A. Burt set a Cedar post with ties:

14" Cedar	S 78°E	14 links
10" Maple	N 14°W	24 links

I found no record of Subsequent restoration.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I found no evidence of the original corner or accessories. At the corner position I found a 1" O.D. pipe with grown over blazes facing the pipe. The pipe also falls on a North - South blazed blue painted line. The pipe works very well with GLO distances to Section Corners North & South. I accepted the 1" iron pipe as the section corner and Monumented it as such.

Research on file with County Remonumentation Representative.

DEED GROUP APPROVED

Earl W. Applebaum
COUNTY REMONUMENTATION
11-29-00

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner is a 5/8" x 48" iron pin with a 3" diameter aluminum cap placed on it, driven inside of a 1" iron pipe. Cap is stamped to read: COUNTY REMONUMENTATION; T48N, R42W, R41W; 1/4; S. 36, S. 31; 2000; P.S. 37273. Ties:

9" Cedar	N 10°E	17.16'
8" Cedar	S 70°E	17.51'
Steel Sign Rail	South	0.67' (to face)
8" Cedar	N 33°W	4.63'
SW Cor. Sec. 31	S 00°01'20"W	2628.44'
NW Cor. Sec. 31	N 00°04'13"W	2633.71'



NOTE: Bearings to witness objects are magnetic. Distances are to a nail in side of the witness object unless noted. Bearings shown between corners are on assumed basis, for reference only.

Signed by *Joseph C. Domitrovich*

Date 11/28/00

Surveyor's Michigan License No. 37273