LAND CORNER RECORDATION CERTIFICATE

REMONUMEN TATION

MAR 02 2001

Compression.

•		Filing Requirement of Act 74, I	Mich. P.A. 1970 ,	SECTION	
<u></u>	Located in:	Corner Code #	JUDITH D. ROE	EHM	

ONTONAGON	Located in:	Corner Code #	
(County)			JUDITH D. ROEHM
1. Public Land Survey	T <u>48N</u> R <u>407</u> T <u>49N</u> R <u>407</u> TR TR		Ontonagon County Page 1 of 1 JEM Date 12/07/2000 Time 14:41:25 RECORDING FEE: 9.00
Property Controlling in Section Miscellaneous Property in Sec.	STR STR STR STR		Register of Deeds Stamp & File Number

. Lot No	, Recorded Plat
. Private Claims	

1/4 Corner common to Sections 5 & 32, T48N T49N, R40W.

I, Earl W. Applekamp , in a field survey on Nov. 01 , xx do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

1 A 1	ВС	D I	E F	GН	ΙJ	K L M
-]	Ţ				
1	5t	— 5 I	-1-	3-	2	1-1-
3	\vdash		 -	1		
4	?+	— ģ-—	ۈ	10		1/2
5	H	_		- 		
61	<u> </u>	_17	16	 15	14	13
7		\perp		1_1_		
81	ا ا	_20		22_	23_	
9		Ī	Ī	l ï	1	1 1
					Ħ	1
103	0	-29-	—-2 8	27—	26-	-25-
11		$\dashv \dashv \dashv$	+	1-1-		
123	ı	_32	33	34	35_	36
13		4				LÎ

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established by John Burt, U.S. Deputy Surveyor, July 1847. Set Yellow Birch Post.

ORIGINAL BEARING TREES:

For corners in

6" Y. Birch N60°E 40 Links (26.40 Feet) 8" Y. Birch N60°W 22 Links (14.52 Feet)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No original bearing trees or evidence was found. Timber was cut 2 years ago South of this Corner. Corner was re-established on line and equal distance between opposite corners East and West.

Research on file with the Ontonagon County Remonumentation Program Representative.

COURTE TOURSHARE

^	escription of monument for corner and accessories established to perpetuate locating the position of the corner
U.	eschollor of monument to comer and accessores established to berbetilate incating the boetlon of the come

At the corner position I set a $2\frac{1}{2}$ "X30" split base aluminum pipe with a 3" Cap stamped to read: County Remonumentation, T48N, T49N, R40W, 1/4, 2000, P.S. 17610. I established three bearing trees and a reference object.

Nail in 7" Maple S05°W 20.24' - Nail in 8" White Ash N81°E 43.17' N45°W 37.88' - 6' Steel Sign Post, North 0.58' Nail in 6" W. Ash



Signed by <u>Cacl</u> W	anslekano	Date November 25, 2000	
Surveyor's Michigan License No	77 47610	^ .	