

JUDITH D. ROEHM  
Ontonagon County  
LC 5/337  
as of 1  
Date 09/06/2000 Time 09:50:17  
9.00  
RECORDING FEE:

SURVEY &  
REMONUMENTATION

MAR 02 2001

SECTION

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

For corners in

Ontonagon County

Located in:

Corner Code #

1. Public Land Survey

2. Property Controlling  
in Section

3. Miscellaneous  
Property in Sec.

4. Lot No.

5. Private Claims

Recorded Plat

I, Joseph C. Domitrovich, in a field survey on July 4, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(B-7) 1/4 Corner Common to Sections 18 & 19, T51N, R38W.

1846 - S.W. Higgins set a 1/4 post with ties:  
10" Balsam N 70°W 25 links  
6" Balsam S 75°E 11 links

1966 - C.C. Lindgren, R.L.S. #14098, for Michigan State Highway Department, found a 1 1/2" iron pipe with a Forest Service location poster. He gave distances to Sections Corners to the East and West. Ties:

3" Ironwood N 70°W 21.74'  
3" Maple S 20°E 13.31'  
4" Maple N 60°E 13.83'

DEED GROUP APPROVAL  
Earl W. Rappaport  
COUNTY REGISTRAR  
8-23-00

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I found no remains of the original corner or accessories. I recovered the iron pipe as called for by Lindgren and 2 of his bearing trees. Distance west from this 1/4 corner to the SW Corner of Section 18 is 507.80' shorter than the GLO distance, however this type of discrepancy is not inconsistent with work done elsewhere in this township by the original surveyor. The pipe has been in place for many years and falls in line with the remains of a fallen E-W fence. Foresters have used it to mark lines in Sections to the North and South. The Sections Corners to the East and West were pipes re-established from original evidence and it is very possible that this pipe was also reset from original evidence at the same time. I have accepted the iron pipe as the best remaining evidence of the original 1/4 corner and have Monumented it as such.

Research on file with County Remonumentation Representative.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner is a 3/4" x 48" aluminum rod with a 3" diameter aluminum cap stamped to read: COUNTY REMONUMENTATION; T51N, R38W; S. 18, S. 19; 1/4, 2000; P.S. 37273. Ties:

6" Hard Maple	N 73°E	13.84'	(M.S.H.D. - added new nail)
5" Ironwood	N 72°W	21.75'	(M.S.H.D. - added new nail)
3" Ash	North	7.79'	
Steel Sign Rail	North	0.70'	
SW Cor. Sec. 18	S 86°34'50"W	2239.12'	(2746.92' GLO) (2239.62' Lindgren)
SE Cor. Sec. 18	N 86°19'38"E	2646.71'	(2640 GLO) (2646.83' Lindgren)

NOTE: Bearings to witness objects are magnetic. Distances are to a nail in side of the witness object unless noted.

Signed by

Date

Surveyor's Michigan License No. 37273

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971  
REVISED MAY 14, 1975  
REVISED JAN. 1983  
REVISED OCT., 1985

