

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

Ontonagon County

Page 1 of 1

LC 5/291

Date 06/12/2000

Time 16:31:53

RECORDING FEE:

9.00

For corners in

Ontonagon County

Located in:

Corner Code #

1. Public Land Survey

T52N R39W

M-5

T52N R38W

A-5

T R

T R

2. Property Controlling
in Section

S

T R

S

T R

3. Miscellaneous
Property in Sec.

S

T R

S

T R

4. Lot No.

, Recorded Plat

5. Private Claims

SURVEY &
REMONUMENTATION

MAR 02 2001

SECTION

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	N
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Joseph C. Domitrovich, in a field survey on May 22, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(M-5) Corner Common to Sections 12 & 13, T52N, R39W & Sections 7 & 18, T52N, R38W.

1845 - William A. Burt set a Hemlock post with ties:

18" Hemlock	S 49°E	41 links
10" Hemlock	N 14°W	22 links

I found no record of Subsequent Restoration.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I found no remains of original corner or accessories. Sylvester Hoffman, a longtime resident of the area told me that he remembered there being an "iron stake" at this corner. I recovered a 2" diameter mushroomed pipe at the corner. A very old fence runs North and South from the pipe. The pipe works well with other corners in the area as well as with occupation. I accepted the iron pipe as the true section corner.


Research on file with County Remonumentation Representative.

PEER GROUP APPROVED
Earl W. Applekamp
COUNTY REMONUMENTATION 5-24-00

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner is a 3/4" x 48" aluminum rod, driven inside a 2" iron pipe, with a 3" diameter aluminum cap stamped to read: COUNTY REMONUMENTATION; T52N, R39W, R38W; S. 12, S. 13, S. 7, S. 18; 2000; P.S. 37273. Ties:

20" Basswood	S 52°E	26.74' (Not Blazed)
6" Balsam	South	13.25'
6" Hard Maple	S 58°W	3.90'
Sign Rail	West	0.90' (To Face)
6" Hard Maple	N 28°W	5.36'
NW Cor. Sec. 13	S 89°44'18"W	2628.04'
E 1/4 Cor. Sec. 13	S 00°23'27"W	2648.93'



NOTE: Bearings to witness objects are magnetic. Distances are to a nail in side of the witness object unless noted.

Signed by

J. C. Domitrovich

Date

5/24/00

Surveyor's Michigan License No. 37273