Ontonason County

LAND CORNER RECORDATION CERTIFICATE: 1
Filing Requirement of Act 74, Mich. P.AE 1974 07/10/2000
RECORDING FEE:

LC 5/320 Time 12:13:40 9.00

For corners in

**Ontonagon County** Located in: Corner Code # T52N R39W ( 1. Public Land Survey **T52N R38W** T R T R 2. Property Controlling S Т R in Section S Ţ R 3. Miscellaneous S R S Property in Sec.

SURVEY &

MAR 02 2001

SECTION


Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

I, Joseph C. Domitrovich, in a field survey on June 16, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 comers, all in the same town and range, may be recorded on this certificate.



A. Description of original monument and accessories and/or subsequent restoration:

(M - 7/A - 7) Corner Common to Sections 13 & 24, T52N, R39W, and Sections 18 & 19, T52N, R38W,

1845 - William A. Burt set Hemlock post with ties:

12" Yellow Birch 14" Hemlock

N 42°E N 07°W 10 links 22 links

1846 - Sylvester W. Higgins added 2 B.T.s:

24" Sugar 14" Y. Birch S 40°E N 42°E

B. Description of comer evidence found and/or method applied in restoring or reestablishing corner:

21 links

.

At the corner position I found a % O.D. x 36" iron pipe. Distances from this pipe work well with recovered remains of 2 of the original bearing trees. The first is Burt's 12° Y. Birch which is now rotten to ground level with roots remaining. The second is Higgins' 24" Sugar which is now a large rotted stump. Distances from this pipe to corners North, South and West work well with GLO. I replaced the pipe with a County Monument.

Research on file with County Remonumentation Representative.

C. Description of monument for comer and accessories established to perpetuate locating the position of the comer:

Corner is a 2 ½" x 30" Aluminum pipe with a 3" diameter aluminum cap stamped to read: COUNTY REMONUMENTATION; T52N, R39W, R38W; S. 18, S. 19, S. 13, S. 24; 2000; P.S. 37273. Corner falls on a point on a ravine with land sloping to North and West. Ties:

N. 470E

5.80'

7" Hard Maple N 17°E 5.80 14" Hard Maple \$ 75°E 15.53 12" Yellow Birch S 07°E 13 48 Steel Sign Rail South 0.681 10" Hard Maple S 61°W 9.35' E 1/4 Cor. Sec. 13 N 00°35'29"W 2646.98' (2640' GLO) E 1/4 Cor. Sec. 24 2641.50' (2640' GLO) S 00°22'09"W NW Cor. Sec. 24 S 89°45'54"W 5245.12' (5264.16' GLO)

NOTE: Bearings to witness objects are magnetic. Distances are to a nail in side of the witness object unless noted.

Signed by the C. Dan h

Date 4/21/00

Surveyor's Michigan License No. 37273

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1972 BENEED MAN 1972

JOSEPH

DOMITROVICH

LAND SURVEYOR

37279

CANDS