

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Osceola  
(County)

Located In:

Corner Code E-1

- |                                    |   |     |     |     |
|------------------------------------|---|-----|-----|-----|
| 1. Public Land Survey              | T | 18N | 10W | E-1 |
|                                    | T |     |     |     |
|                                    | T |     |     |     |
|                                    | T |     |     |     |
| 2. Property Controlling in Section | S | T   | R   |     |
|                                    | S | T   | R   |     |
| 3. Miscellaneous                   | S | T   | R   |     |
| Property in Sec.                   | S | T   | R   |     |

APPROVED LAND CORNER  
P.A. 345 OF 1990  
Osceola County

19 OCT. 1995  
*Matthew McClung*  
Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

Matthew McClung October 14, 1995

I, \_\_\_\_\_, in a field survey on \_\_\_\_\_, 19\_\_\_\_\_, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:

The original corner was set by deputy surveyor John Hodgson on 10 June 1838. Set wood post 81.70 chains from South 13 lks West of post. Hemlock 20" for post corners Section 4 and 5.

I have shown 1 LCRC by Hooth.

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1" bar, 2 feet East of center line, 1" below surface. Excavated to 14" into subsoil and found no other evidence of corner. 14" cedar fence post to West, with State Tag. Corner is 8.52 feet West of LeRoy Corner. Bent bar and placed Osceola County Monument over position of bar 6" below surface.

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner E-1. Osceola County Monument, which is a 3" brass cap mounted on a 1" pipe 18" in length.  
18" Cedar fence post West 32.30 feet.  
12" Cherry N 30W 53.01 feet.  
6" White Pine N30E 46.10 feet.  
4" Ash S52E 36.60 feet.



OSCEOLA COUNTY  
REGISTER OF DEEDS  
MAR - 7 AM 10:22  
*Matthew McClung*

Signed by *Matthew McClung* Date October 14, 1995  
Surveyor's Michigan License No. 13037