LAND CORNER RECORDATION CERTIFICATE

		ER RECORDATION CERT		
For corners in 0scoda	Located in:	Corner Code #		
(County) 1. Public Land Survey	T <u>26 N</u> R <u>2 E</u> T R	Н-13	Libe	- 4 pg. 100.
Property Controlling in Section Miscellaneous Property in Section	T R T R S T R S T R S T R			STATE OF MICHIGAN OSCODA COUNTY FILED 19 SEP 95 4:04 P.M.
•	STR			s Stamp & File Number
4. Lot No, Rec 5. Private Claims I,Larry G. Beauregard in			A B C 2 6	RESISTER OF BEEDS DEFGHUJKLM 5 10 11 12 12
do hereby certify that under requi in lines 1 and 2 above were in cormanual of survey instructions. Management or by a decree of a 5 above were in conformance w. Decree of a Court of Law; establias expressed below:	rements of P.A. 74, Michigan P./ Iformance with regulations and r of the United States Departm Court of Law and/or that the co ith the rules of the Michigan Bo shed, re-established, monumen	A. of 1970, the corner points menules therefore as required in the other of the Interior, Bureau of other points mentioned in lines 3, pard of Professional Surveyors of ted, re-monumented, recovered,	turrent Land 4 and 5 19 2 found	7 — 16 — 15 — 14 — 13 — 10 — 21 — 22 — 23 — 24 — 1 — 1 — 1 — 1 — 1 — 1 — 1 — 1 — 1 —
NOTE: Not more than 4 come on this certificate.	ers, all in the same town and	range, may be recorded	12 31 3	2 33 34 35 36
A. Description of original materials. Lewis Clason, Dep (\$ 27° W 66 links 12" Asp 1-9 & 10-1884, John Randall (N 26½° W 10½ links 6" B.	outy Surveyor, set ‡ Sectoen). Den). , County Surveyor, marke	tion post. Witnesses mar	ked: ृ(\$ 68° E 18 li	
9-28-1914, C.O. Seeley, Cou with moss, identified as sa (present measurement agrees T 26 N, R 2 E, with 2" iror 12" Aspen).	nty Surveyor, found 10" me, (S 27° W 66 links with U.S. on entering s	12" Aspen-gone). Indica wamp). Set new post of (tions are that the sw Cedar at 1 corner on	ail is very wet at times, South side of Section 34.
1924, Guy R. Veal, Dependen an iron post, 3' long, 1" o the ‡ Section corner of Sec	liam., 27" in ground for	witness corner to the rea	stablished 1 Section	corner of Section 34 and
4-23-1969, Norman C. Caldwe GLO dependent resurvey did by the Road Commission. No Records.	not place this corner du	e to a small pond which h	nas since been filled	in by road construction.
9-6-1977, Norman C. Caldwel Records. No references mar	1, P.S. #12018, found 2" ked.	pipe of Record. Boundar	y survey, Recorded L	. 2, P. 406, Oscoda Co.
9-20-1978, Norman C. Caldwe Records. No references mar	II, P.S. #12018, found 2 ked.		ry survey, Recorded I	
SEE BACK OF SHEET FOR SECTI C. Description of monument South 1 corner for Section	for corner and accessories	established to perpetuate lo	catiodin by since Abth	unentation
Oscoda County Remonumentations. Accepted as a careful July 14, 1995.	on cap P.S. #18654 on a	5/8" x 18" bar inside a 2 ent of the position of th	Peer Review " x 12" pipe, this all e corner. Approved f	ll being inside a monumer
6 60° E 85.10' Power Pole 6 10° E 76.15' 7" Oak 6 60° W 87.93' 14" W. Pind 1 25° W 61.55' 8" Elm) Ex. 2" pipe & cap - Placed P.K. nail & P. -Placed 60d spike and P	.S. tag #18654 (typ)	LARRY G. BEAUREGARD SURVEYOR NO. 18654	
Signed by Sany.	DBeausyan	Date	ONAL SU	9/8/95
Surveyor's Michigan License N	Deausyan 1018654	FORM APP	ROVED BY MICHIGAN STATE BOARD OF F	PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN. 1983

26N 2E H-136

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Existing 2" pipe placed by Norman Caldwell in 1966 by single proportion method 0.5' North of Co. Rd. centerline.

Oscoda Co.

Ser year old

3