## SURVEY & REMONUMENTATION

APR 2 4 1995

Private Claims \_\_

## COMMISSION

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

1,1000	4
Liber Page	ľ
rage	1

1-0	or corners in	•		$\sim$
	Oscoda (County)	Located In: Big Creek Twp.	Corner Code =##	STATE OF HICHIGAN OSCODA COUNTY
1.	Public Land Survey	T <u>26N</u> R <u>2E</u>	<u>(I-2)</u>	FILED
	•	T R T R		3 NOV 94 9:28 A.H.
_	D O tralling	T R		PATSY J. PETERS
2.	Property Controlling in Section	S T R S T R		REGISTER OF DEEDS
3.	Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp & File Number
Ā	t at No.	Boogrand Plat	-	

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:
- (I-2) Wood  $\frac{1}{4}$  section post set by William R. Coon in 1839.

Wits: 10" Aspen N 794° W 12 links

6" Aspen S 68° E 13 links

Guy R. Veal in 1935 found  $1\frac{1}{2}$ " x 8" iron pipe above ground set by engineers of Consumers Power Co. from original evidence in 1909. Set a regulation iron post 1" diam., 24" long in a conc. mon. 24" long, 6" diam., 18" in ground with brass cap marked Secs. 2 & 3. Government Deputy Surveyor. Dependent Resurvey of T26N, R2E. Wits: (6" Poplar N 79° E 18 links)  $(7" Poplar S 15\frac{1}{4}° W 14 links)$ 

Norman C. Celdwell P. S. #12018 between 1968–1981 found U.S. GLO mon. No references marked. Corner Registry recorded L.2, P. 93 in April of 1969.

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (I-2) Found U.S. GLO man. set in 1935 from Dependent Resurvey by Veal. Man. in good condition  $3^{1\pm}$  E. of corner fence post, 12"± above ground. No 1935 wits. found. Placed  $\frac{1}{2}$ " x 18" bar alongside monument.

## **APPROVED**

County Remonumentation

Peer Review Group

NCC 3/06794



- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- (I-2) ½ corner common between Secs. 2 & 3, T26N, R2E.

U.S. GLO monument set in 1935 from Dependent Resurvey by Veal is in good condition and is  $3' \pm E$ . of corner fence post,  $12" \pm a$  bove ground, and is accepted as a careful and faithful perpetuation of the position of the original corner. (Placed  $\frac{1}{2}" \times 18"$  bar alongside monument).

7" Ash N 40° E 14.68' 9" Ash S 55° W 18.10' 4" Birch N 60° E 24.13' 5" Ash 5 60° E 27.33'

Placed blaze, 20 penny spike and P.S. tag #18654 (typ).

Signed by Sarry Seaway are Date Surveyor's Michigan License No. 18654	- 10/21/94
Surveyor's Michigan License No. 18654	FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971