Cons. 4047 Rev. 10/60

## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

T. 28 N.R. 3 E

			0scods		COUNTY
DESCRIPTION OF CORNER _	Section corner common	to Sections	32-33 on	South Boundary	
CORNER MONUMENT	Replaced 2" pipe with	Cons. Dept.	Monument		<del></del>
DATE MONUMENT PLACED AND WITHESSED 11/7/68					
WITHESSES TO CORNER					<del></del>
N I	* 9" R. Oak		n 47 e	26.4'	. <del></del>
32	6" R. Oak		N 35 W	4.51	
CIRCLE CORNER REGISTERE	AND  * Henning witnes	18			

DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found during a survey in this area. Found 2" pipe presumably as established by G. D. Henning in a previous survey of record, which has been used in further corner location and subdivision of Section 4. Although a point was located some 25' NW which may have been Seeley's position for this corner, it was conclude that since positive identification is impossible, and a number of recent surveys were all based on the Henning location for purposes of section subdivision, we are led to disregard the possible Seeley corner in favor of the one identified in this record.

SURVEYOR'S SEAL

SIGNED LEWELL SURVEYOR 10068 PATE 11/27/68