

FEB 24 2000

SECTION

OTTAWA COUNTY REMONUMENTATION
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED
99 OCT 27 PM 1:49

For corners in

Ottawa

(County)

Located in:

Corner Code #

1. Public Land Survey

T5N R15W

B-3

T R

T R

T R

North 1/4 corner

Section 7

Holland Twp.

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

Sam S. S. S.
REGISTER OF DEEDS
OTTAWA COUNTY, MI

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

I, Steve Lampen, in a field survey on September 15, 1999,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as
expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

B-3	L.C.R.C. - L1, P503 - Clapp - 1972	L.C.R.C. - L2, P679 - Clapp - 1974
GLO - Brookfield - 1832	Found T iron	Set cast iron monument
Set 1/2 mile post	Power pole S 59.57	Transmitter pole SSE 25.60
Maple 10 N 43 W 30	Guy pole SE 71.80	Guy pole SE 71.80
Maple 10 S 33 E 26	Power pole N 66.91	Power pole N 66.91

Peck - 1890's±	L.C.R.C. - L6, P345 - Brintnall - 1998
Stone	Set 1/2" iron in monument box
B-3 to A-3 = 41.17 ch	N 50° W 66.98 Found PK SW side 16" Elm
B-3 to C-3 = 40.04 ch	N 5° E 66.97 Found nail and tag S side Power pole
	S 70° E 71.80 Found nail and tag N side Guy pole
	S 20° E 25.60 Found nail and tag N side Power pole
	North 100.00 set 1/2" iron with cap
	North 200.00 set 1/2" iron with cap

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

B-3 Found 1/2" iron in monument box	Transmitter pole SSE 25.60	Power pole N 66.91
N 50° W 66.98 Found PK SW side 16" Elm	North 100.00 Set 1/2" iron with cap	North 200.00 Set 1/2" iron with cap
N 5° E 66.97 Found nail and tag S side Power pole		
S 70° E 71.80 Found nail and tag N side Guy pole		
S 20° E 25.60 Found nail and tag N side Power pole		

B-3 to C-3 Peck = 40.04 ch (2642.6) meas. = 2643.08
B-3 to A-3 Peck = 41.17 ch (2717.2) meas. = 2723.65

Replaced 1/2" iron with an Ottawa County Remonumentation iron and cap and accepted it as a careful and
faithful perpetuation of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

B-3 Ottawa County Remonumentation iron and cap in a monument box

Azimuth = Michigan State Plane grid direction

Remonumentation tag in SW side 16" Ash	313° 54'	66.97
Remonumentation tag in N side 16" Ash	297° 09'	113.93
Remonumentation tag in NE side Power pole	161° 19'	25.96
NE corner house foundation	147° 14'	105.16
NW corner house foundation	157° 38'	88.59
Capped iron	2° 34'	100.00 + 200.00

Signed by Steven Lampen

Date OCTOBER 25, 1999

Surveyor's Michigan License No. 37279

Liber 4 Page 440

